

Internal Audit Check list

Calibration Index

VST

Created:	17/May 1995	Audit No 6	VM3/COP11 VOP11
Revised:	17 August 2016	Last printed 19/08/2009 03:47:32 PM	Page 1 of 1
Audit Date	17-8-16	Auditor <i>Hebe (cmh)</i>	ISO 6.3 7.6

Role ID 80

Calibration register has been transferred to Intrastats.

Out of calibration test equipment automatically flags when it is requested for use.

Verify the existence of a calibration register and planned matrix	Done in Intrastats	N/A
Is the register maintained. This can be found on Intrastats in ISO – Calibration Index <i>Black box for batch and Black case R+D room not to be</i>		
Check QA, R + D Room, Workshop etc. for equipment that does not have a Viamed Bar Code CE sticker. <i>Black box TSL Search – item being developed Black case R+D room – borrowed not VST equipment</i>		Y
Is equipment calibrated within its due period	Done in Intrastats	
Verify that records show any measurements taken. And parameters stated.	Done in Intrastats	
Is the register updated with this information	Done in Intrastats	
Verify that where items which failed calibration are assessed to ascertain potential recall of product.	<i>none current</i>	N/A
Are Calibrations traceable to NAMAS Standards. <i>UKAS #77072</i> <i>* need a report to show these</i>		Y
Are In-House calibration procedures listed in the Intrastats Document Index where required. <i># 77071</i>		Y