

## Memo From Peter

**Date:** 17-5-94

**To** John

Points to bear in mind re Tomthumb

- 1) Staff may connect the Tomthumb to their flowmeter while set at maximum therefore putting a large surge on the manometer (this happened in South Shields)
- 2) There is no indication of the inlet or the outlet
- 3) No instructions or service details supplied with some units
- 4) Maximum fixed pressure relief can easily be adjusted
- 5) Circular label shows how to reduce pressure- normally arrows indicate how to increase pressure

mem17594