

Service Repair Sheet SRS68348

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Paul Denyer
Crawley Hospital
EME Department
EME Services Technician
01293 600300

00001300
paul.denyer@nhs.net

19/Dec/2022
Robert Connor
Viamed
Quote

VIAMEDclean

Goods In Only
Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 13/Dec/2022 Sophie Lines

13/Dec/2022 Sophie Lines

Returning Microstim DB3 - serial number M0005254 - has the following faults:

When the P.T.C 1 Hz switch is activated you don't always get an output voltage, this is the case if the switch is operated in either direction. The other switch also occasionally fails to operate.

I advised the fixed cost repair service

19/Dec/2022 Robert Connor

Received 1 x DB3 s/n M0005254, with 9v battery

Ready For quote

Cgreen 3-1-23

Repair Complete Signed

Cgreen 24-1-23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35559	Microstim DB3	2510000	M0005254	N

2540010 x1 EAS
S/N, SRS, SRN

UPS x1 @ E12.

PURCHASE ORDER

Page 1 of 1

SURREY & SUSSEX HEALTHCARE NHS TRUST



Supplier: VIAMED LTD 15 STATION ROAD CROSS HILLS KEIGHLEY, WEST YORKSHIRE BD20 7DT 01535634542	
Buyer	HAYLEY RTP BROWN
Telephone	
Email	hayley.brown26@nhs.net
RTP0121 EME DEPT ESH	

Deliver to:
EAST SURREY HOSPITAL
GOODS INWARDS
CANADA AVENUE
REDHILL, Surrey RH1 5RH

Invoice to:
SURREY & SUSSEX HEALTHCARE NH
RTP PAYABLES Z955
PHOENIX HOUSE, TOPCLIFFE LANE
WAKEFIELD, WF3 1WE
0303 123 1177
GLN:

Order Number	106283264
Date	09-JAN-23

1. Goods will be received only between 08.30 and 16.00 hours Monday to Thursday and between 08.30 to 15.30 on Fridays
2. The Official order Number MUST be quoted on all delivery notes and invoices
3. It is a condition of this order that the property & risk of the goods shall lie with the supplier until the goods have been examined and accepted at the specified delivery address as per the contract conditions.
4. Control Of Substances Hazardous to health (COSHH) - a full material data sheet must be forwarded for each product on the occasion of the first order - or on request of an authorised officer.
5. Order is conditional on Medical Devices being CE marked in compliance with directive 93/42/EEC or other as determined by the UK MRHA

Quantity Required	U.O.M	Supplier Part Number:	Description	Delivery Date	Unit Price (Inc Discount)	Line Value GBP
1 EACH			COMPANY ENGINEER TO SIGN IN AT EME BEFORE COMMENCING ANY WORK AND ALL SERVICE REPORTS TO BE SIGNED FOR. AND GIVEN TO. EME SERVICES OR EMAILED TO sash.eme.helpdesk@nhs.net	23-JAN-23	0.00	0.00
1 EACH			PLEASE REPAIR NERVE STIMULATOR MODEL MICROSTIM DB3 SERIAL NUMBER M0005254 AS PER QUOTATION REF QVM141182	23-JAN-23	57.00	57.00

Total Value of Order (Exc VAT) 57.00

Instructions to Supplier: This order is subject to the standard NHS Terms and Conditions of contract. For a copy of these please contact the Buyer for this order. Any price alterations must be agreed with the buyer prior to order execution. The above order number must be quoted on all invoices, acknowledgements, delivery notes and other correspondence. A delivery note must accompany each consignment of goods. The order must not be passed to any third party for supply. Any invoices not complying with these instructions will be returned unpaid to the supplier.

Service Repair Sheet 68348

Contact Name	Paul Denyer
Company/ Hospital Name	Crawley Hospital
Department	EME Department
Position	EME Services Technician
Direct Phone	01293 600300
Opera Account	00001300
Email	paul.denyer@nhs.net
Order Number	106283264
Date Received	19/Dec/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN35559	2510000	M0005254	Microstim DB3	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	2540010
Qty: 1	2510000
Qty: 1	2520000

The Microstim DB3 has been repaired. A new patient lead has also been supplied.
