


* CONNECT INTERVOLTAGE SHIELD OF CABLE TO PIN 7
CONNECT PINS 1 AND PIN 4 TO PIN 7 USING JUMPER

1000
 1000
 1000
 1000


DOS FILE NAME: DOS FILE NAME




CONNECTION CHART

PIN #	WIRE COLOR
1	RESISTOR
2	ORANGE
3	RED
4	N/C
5	WHITE
6	RED/YELLOW SHIELD
7	CABLE SHIELD
8	N/C
9	BLACK


* SEE SCHEMATIC




RESISTOR
7.0K, 1%, 1/4W
(ISOLATE RESISTOR
USING SHRINK TUBING)



ORANGE
WHITE
BLACK
RED



DETAIL A



DETAIL B

REVISION LETTER