



E412-09

Epac Detector
Wiring Diagram

Solder side



- 1 resistor + capacitor
- 2 n/c
- 3 n/c
- 4 link
- 5 link + Outer shield
- 6 Red
- 7 Yellow
- 8 res + cap + white
- 9 Black + inner shield
- 10 n/c

resistor = 16k