

Customer: Divesoft s.r.o. K Haltýři 14 180 00 Praha 8 Identif. number: 26722101 Tax identity: CZ26722101 Telephone: +420416857057 E-mail: cz.info@divesoft.com www.divesoft.com Order No.: 23OB0251 Payment: payment order Order Date: 17.04.2023	Establishment: Roudnice nad Labem Hálkova 2495 413 01 Roudnice nad Labem	Tel.: Supplier: Vandagraph Sensor Technologies 15 Station Road, Cross Hills, Keighley West Yorkshire, United Kingdom Identif. number:
--	---	--

Description	Q'ty	Unit price	Discount	Total
Complain to the order : 22OB0714				
3092:8010020 Oxygen Sensor - type 22D	4 pcs	29.35		117.40
TOTAL DUE		Currency GBP		117.40

Returns number:

Oxygen Sensor type 22D : D109803, D110940, D111154, D111156,

The issue with some sensor is, that sensor haven't connection when the sensor is properly connected to molex connector. When you release the lock of the connector and move with connector to the half way, then the sensor have connection and work properly. All the sensort with this issue are tested also with another molex connectors, but result is still same.

Please confirm the receipt of the complaint and specify the date of the complaint.

Issuer: Katarína Řepová
office.cz@divesoft.com

Recipient:	Official stamp:
Economic and information system POHODA	