Problem with Tek-Ox base battery contacts – to send a new base and some spare screws.

Airmail, make sure his phone number is written on the outside of the parcel