

## Symbols – Oxygen Sensor Label



Warning triangle – indicates ‘Caution, consult accompanying documents’ i.e. instructions, labelling...



General ‘harmful’ warning symbol.



The letters CE are the abbreviation of the French phrase Conformité Européenne (European Conformity). CE marking on the product is the manufacturer’s declaration that the product complies with the essential requirements of the relevant European health, safety and environmental protection legislation - in practice by the associated product directives. The product directives contain the essential requirements and/or performance levels and harmonized standards to which the product must conform.



Manufactured date symbol (factory) and manufactured date format (year—month) in line with EN standards.



Serial number and bar code - standard format . We can accommodate specific serial number formats.