



23.3-99

T C400 RS.

# SECTION CONTROLLER.



Remove 2 x Screws A  
fix Brass-steel Bracket  
using 2 x (N°6 x 2" wood  
Screws



fix 4x6x6 149-690

1x 2050 (CLAMP)

2x PP8652 (BRASS COLLAR)

2x BUTION HEAD BP2

2x WOOD SCREWS

BRASS  
COLLAR

TIME 10 MINS

Have

PT N.O RDO183

Remove clamp.

TIME 1 MIN