Service Repair Sheet SRS68721

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Pierce Laurens

Queen Elizabeth The Queen Moth

EME Department

01843234346

01843225544

00003665

pierce.laurens@nhs.net

44007014

11/Mar/2024

Robert Connor

Viamed

For Servicing

Notes PO received, attached 06/Mar/2024 Kate Griffiths PO received, attached £86.40 incl VAT 11/Mar/2024 Robert Connor

Received 1 x V1000 s/n PR0542A12, with 4 x AA battery, grey silicone cover, and blue fabric carry case. PO included for 86.40 GBP.

Please remind customer that a certificate of decontamination status is required when sending in units.

Ready For quote

Repair Complete Signed

CGNEEN 12.3.24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36308	Foetal Simulator	1410000	PR0542A12	2

14800000 × 1 2 600 SIN, SES, SEN 1430309 × 1 60 SES, SEN UPS × 1 2 612.

Registered Office: Management Offices, William Harvey Hospital, Kennington Road, Willesborough, Ashford, Kent, England, TN24 OLZ, VAT No. GB 297 8726 29



PURCHASE ORDER NUMBER: 44007014

Please quote this reference on all correspondence

Emailed To: orders@viamed.co.uk

VIAMED LTD

15 STATION ROAD

CROSS HILLS

KEIGHLEY

W YORKS

BD20 7DT

Order Date Cost Centre Requisition Number Requisition Point
06/03/2024 4232 64007016 4231 - QEQM EME
0109

Delivery Address:

EME MANAGER HOSPITAL STORES
QUEEN ELIZABETH QUEEN MOTHER HOSPITAL
ST PETERS ROAD
MARGATE
KENT
CT9 4AN

Invoice To:

2GETHER SUPPORT SOLUTIONS LTD
PAYMENTS DEPARTMENT
TRUST OFFICES
KENT & CANTERBURY HOSPITAL
ETHELBERT ROAD
CANTERBURY, KENT
CT1 3NG

Your Reference: VIAMED/612373/6975/PL

Email:

ekfc.payables-2ss@nhs.net

Procurement Enquiries to: Nicola Daines

Tel: 01233 616601 or Email: 2gether.2getherprocurement@nhs.net

If you have an queries regarding the prices quoted, please contact the Buyer named above

POSTAGE & CARRIAGE CHARGES	SN: PR0542A121410000; CALIBRATION CHARGE QUOTE REF; SRS68721	DESCRIPTION	Failure to invoice agreed or
		MPC	ed or contract
-	1	QUANTITY	contract prices may result in delayed payment
ITEM	ITEM	TINU	sult in delaye
12.00	60.00	PRICE	d payment
		DISC %	
12.00	60.00	AMOUNT	

Signed:

John Comment

Managing Director

Order Total (ex VAT)

VAT Total

Order Grand Total

72.00

14.40 86.40



Viamed Limited · 15 Station Road · Cross Hills
Keighley · West Yorkshire · BD20 7DT · United Kingdom
Keighley · West Yorkshire · BD20 7DT · United Kingdom
Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582
Email: info@viamed.co.uk Website: www.viamed.co.uk

THE REPORT OF THE PARTY OF THE

Service Repair Sheet 68721
Contact Name
Company/ Hospital Name
Department
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received

Pierce Laurens
Queen Elizabeth The Queen Mother Hospital
EME Department
01843234346
01843235544
00003665
pierce.laurens@nhs.net
11/Mar/2024
Robert Connor

Repair Ref S/N Equipment Type SRN36308 1410000 PR0542A12 Foetal Simulator

Complete - Repaired

Time: 0 Hour(s)

Booked in By

Parts Replaced

V1000 has had transducer interface cushion replaced and calibration has been checked.