

Viamed Limited · 15 Station Road · Cross Hills
Keighley · West Yorkshire · BD20 7DT · United Kingdom
Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582
Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68845

Contact Name

Company/ Hospital Name

Department
Position
Direct Phone
General Phone
Opera Account

Email

Order Number Date Received Booked in By Preye Tokoro

Homerton Hospital

Dept of Clinical Engineering Senior Medical Technical Officer

02085107143 02085105555 00002950

preye.tokoro1@nhs.net

334107986 16/Jul/2024 Robert Connor

Repair SRN36533 Ref

S/N

1410000 PR02260A14

Equipment Type Foetal Simulator

Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 1430309 Qty: 1 1480000

V1000 has had transducer interface cushion replaced and calibration has been checked.