

ESTIMATED COST SAVINGS
- REPLACEMENT COMPONENT PARTS FOR MICROSTIM DB MODIFIED BOARD LAYOUT -

PART NO.	DESCRIPTION	COST (Using Microstim DBS price list May 1995)	REPLACEMENT PART (Using Farnell catalogue April 1999)	FARNELL PART NUMBER	FARNELL ONE OFF PRICE	ESTIMATED SAVING
		£			£	
DB03	10K resistor	0.02	Not Required		0.00	
DB12	0.33uF capacitor	0.84	Not Required		0.00	
DB17	12pF capacitor	0.07	Not Required		0.00	
DB18	12pF capacitor	0.07	Not Required		0.00	
DB41	6 MHz crystal	0.77	4 MHz crystal	492-917	0.57	
DB32	40 pin IC socket	0.85	18 pin IC socket	877-372	0.24	
DB31	IC TMS77C82	9.92	IC PIC 16F84	789-586	3.47	
		£12.54			£4.28	£8.26