



Work Instructions & Test Methods

Select material 4mm Perspex Clear Cast
Refer to customers/master drawing
Using heater and jigs bend perspex along drawn lines
Smooth all edges with fine emery paper and flame polish
Clean and polish
Assemble as per instructions

QA

Check finished product against customers/master drawing
Check all edges for smoothness
Check that no imperfections are present

Wrap in protective wrapping