

We have been having trouble with the R-30V O2 cell, P/N 0110040, 03/2025, I have fitted 2 to a GE Aesys anaesthetic machine and have had a constant leak of 450ml/min, this leak is not present on a 2024 cell or the GE O2 plug fitted, I have swapped O rings and greased with GE Krytox, the leak is still there on the 2025 cells regardless. Could you please advise as I don't want to open anymore new cells.

S

**Steve** 3:47 PM

If you wish I will reply to Martin, please forward the email to me. Also, please send him FOC 2 x 0120091 Oxygen sensor O ring for R-30V