Service Repair Sheet 69167

Contact Name Matthew Jameson

Company/ Hospital Name Sunderland Royal Hospital

Department Clinical Engineering

Position Senior Clinical Engineering Technician

 Direct Phone
 01915699933

 General Phone
 01915656256

 Opera Account
 00004992

Email matthew.jameson@nhs.net

Order Number RLNP400126294
Date Received 02/Jul/2025
Booked in By Robert Connor

Repair Ref S/N Equipment Type

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 040026 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair Ref S/N Equipment Type

SRN37971 0310030 040090 Tom Thumb Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1 0380000 Qty: 1 0330203 Qty: 1 0330212

Tom Thumb TT480 040090 has been stripped and cleaned then reassembled with new O rings and a new gauge. The two valves have been checked and reset before QA.

Repair Ref S/N Equipment Type

SRN37972 0310030 VMA113 Tom Thumb Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 VMA113 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair Ref S/N Equipment Type

SRN37973 0310030 VMA0084 Tom Thumb Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 VMA0084 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Service Repair Sheet 69167

Contact Name Matthew Jameson

Company/ Hospital Name Sunderland Royal Hospital

Department Clinical Engineering

Position Senior Clinical Engineering Technician

 Direct Phone
 01915699933

 General Phone
 01915656256

 Opera Account
 00004992

Email matthew.jameson@nhs.net

Order Number RLNP400126294
Date Received 02/Jul/2025
Booked in By Robert Connor

Repair Ref S/N Equipment Type

SRN37974 0310030 VMA115 Tom Thumb Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 VMA115 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair Ref S/N Equipment Type

SRN37975 0310030 VMA9001 Tom Thumb Complete - Repaired

Time: 0 Hour(s)

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 VMA9001 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair Ref S/N Equipment Type

SRN37976 0310030 VMC9072 Tom Thumb Complete - Repaired

Time: 0 Hour(s)

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 VMC9072 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair Ref S/N Equipment Type

SRN37977 0310030 VMA0103 Tom Thumb Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 0380000 Qty: 1 0330236

Tom Thumb TT480 VMA0103 has been stripped and cleaned then reassembled with new O rings and a new gauge face. The two valves have been checked and reset before QA.

Service Repair Sheet 69167

Contact Name Matthew Jameson

Company/ Hospital Name Sunderland Royal Hospital

Department Clinical Engineering

Position Senior Clinical Engineering Technician

 Direct Phone
 01915699933

 General Phone
 01915656256

 Opera Account
 00004992

Email matthew.jameson@nhs.net

Order Number RLNP400126294
Date Received 02/Jul/2025
Booked in By Robert Connor

Repair Ref S/N Equipment Type

SRN37978 0310030 VMA0107 Tom Thumb Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 VMA0107 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair Ref S/N Equipment Type

SRN37979 0310030 VMA0111 Tom Thumb Complete - Repaired

Time :0 Hour(s)

Parts Replaced

Qty: 1 0380000 Qty: 1 0330236

Tom Thumb TT480 VMA0111 has been stripped and cleaned then reassembled with new O rings and a new gauge face. The two valves have been checked and reset before QA.

Repair Ref S/N Equipment Type

SRN37980 0310030 VMA0112 Tom Thumb Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 VMA0112 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.