



Aqib Majeed <viamed.aqib.majeed2@gmail.com>

Datex Aestiva 5 Replacement O2 Sensor (19587)

Jon Wood <jon.wood@certusbiomed.com>

Tue, Sep 23, 2025 at 10:53 AM

To: Aqib Majeed <viamed.aqib.majeed@gmail.com>

Hello Aqib,

I hope you're well.

I was wondering if you could help with a replacement O2 sensor for the Aestiva 5 in the attached photos. I think we have ordered R-30V sensors for the Aestiva 5 in the past, could you confirm these are the correct sensors for this particular machine please?

If so, could you quote for one sensor including shipping please?

If the R-30V is not the correct sensor could you quote for the appropriate sensor please?

I can ask the customer to confirm the type of sensor they have if needed.

Thank you.

Regards,
Jon

Should you have an urgent enquiry, please do not hesitate to email contact@certusbiomed.com.

This inbox is manned by a team of customer service advisers and technical staff so your enquiry will be processed in a timely manner.

[Our office hours are variable but there is always someone available between 9am and 5pm Monday - Friday.](#)



Jon Wood

Workshop Administration Assistant

E: jon.wood@certusbiomed.com

P: 0330 202 0366

Unit 7C A30 Business Park Lodge Way Indian Queens
St Columb Cornwall TR9 6FZ

www.certusbiomed.com



ISO 9001: 2015



This communication may contain information that is proprietary, confidential, or exempt from disclosure. If you are not the intended recipient, please note that any other dissemination, distribution, use or copying of this communication is strictly prohibited. Anyone who receives this message in error should notify the sender immediately by telephone or by return e-mail and delete it from his or her computer.

3 attachments



7103326.jpg
178K



7103325.jpg
179K



8063141.jpg
89K