

S/N	生产日期 MFG	故障原因 Problem	产品图片 Product Picture
219380 L4	2024/12	漏液 leakage	
261113 E5	2025/05	电压值偏低 low voltage reading	
261145 E5	2025/05	电压偏低 low voltage reading	
244375 C5	2025/03	首次拆封使用装机测试值低 (标气10%, 测试值7.3%-9.8%不定) the tested reading is below standard in first use	

from: Lifemed Co., Ltd
 Email: info@lifemed.cn
 2025.10.26