

Our Ref: PB/AB/ 1440207
Returns Ref: SRS69373**QMC Campus**
Clinical Engineering
Derby Road
Nottingham
NG7 2UH
Tel: 0115 969 1169 Ext: 6428711th March 2025**F.A.O. Kate Griffiths**
Returns Dept – SRS69373
Viamed Ltd
15 Station Road
Cross Hills
Keighley
West Yorkshire
BD20 7DT

Dear Kate


Faulty Sensor

Asset No	N/A
Manufacturer	Maxtec
Model	Max250E Sensor
Serial Number	LH11099004
Perceived Fault	Attempted to calibrate unit, failed several times, carried out troubleshooting, new sensor is faulty.
Accessories Sent	N/A

The above item has been returned to you for repair. A quotation will be required for any work carried out.

Would you please contact our Chief Technician, **Mr Paul Hook**, on ext. no: **84287**, or email paul.burrows5@nhs.net / paul.hook3@nhs.net with the cost, and confirmation for the work to go ahead? A purchase order number will then be issued.

Yours sincerely

p.h.

Mr Paul Hook
MESU Electronics Team Leader
MESU QMC Campus