

Two questions

Michael Holm <mh@muro-ccr.com>
 To: Steve Nixon <steve.nixon@vandagraphst.com>
 Cc: Ole Stenderup <os@muro-ccr.com>

27 July 2026 at 08:38

Morning Steve

First I'll like to have a status on the MURO sensores.

Next I've got this info from Finnish Navy.

I know the sensores are that ols they should not be used but what about the leaking.

This came from FN...

I received three cells along with the device from the warehouse, as shown in the photos. The cells were in their own packaging, which was completely intact and dated 8/2025. When I opened the first package, I noticed that the cell was covered in a brown liquid. Upon closer inspection, I noticed that the other two had also leaked fluid. The cells are still in my possession, and the second package remains unopened. As I understand it, the products are defective. Should I send the cells somewhere for inspection, or does this require any other action?



Kind regards



MURO-CCR · Industrivej 15 · 8830 Tjele · Denmark

Phone direct: +45 20847000

Email: mh@muro-ccr.com

Web: <https://muro-ccr.com>