		Internal Audit (Check list	
Returns, Repairs & Service				
Created:	17/May 1995	Audit No 11	VOP 09	
Revised:	30 September 2019		Page 1 of 11	
Audit Date		Auditor		

Company / ISO Section	Criteria of ISO Section	Auditor Comments / Issues
VST Ltd	Customer communication	
ISO9001:2015	Communication with customers shall include:	
8.2.1	a) providing information relating to products and services;	
	b) handling enquiries, contracts or orders, including changes;	
	c) obtaining customer feedback relating to products and services, including customer	
	complaints;	
	d) handling or controlling customer property;	
	e) establishing specific requirements for contingency actions, when relevant.	
VST Ltd	Property belonging to customers or external providers	
ISO9001:2015	The organization shall exercise care with property belonging to customers or external	
8.5.3	providers while it is under the organization's control or being used by the organization.	
	The organization shall identify, verify, protect and safeguard customers' or external	
	providers' property provided for use or incorporation into the products and services.	
	When the property of a customer or external provider is lost, damaged or otherwise found	
	to be unsuitable for use, the organization shall report this to the customer or external	
	provider and retain documented information on what has occurred.	
	NOTE A customer's or external provider's property can include materials, components,	
	tools and equipment, premises, intellectual property and personal data.	
Viamed Ltd	Review of requirements related to product	
ISO13485:201	The organization shall review the requirements related to product. This review shall be	
6 7.2.2	conducted prior to the organization's commitment to supply product to the customer (e.g.	
	submission of tenders, acceptance of contracts or orders, acceptance of changes to	

	contracts or orders) and shall ensure that: a) product requirements are defined and documented; b) contract or order requirements differing from those previously expressed are resolved; c) applicable regulatory requirements are met;
	d) any user training identified in accordance with 7.2.1 is available or planned to be available; e) the organization has the ability to meet the defined requirements. Records of the results of the review and actions arising from the review shall be maintained (see 4.2.5). When the customer provides no documented statement of requirement, the customer requirements shall be confirmed by the organization before acceptance. When product requirements are changed, the organization shall ensure that relevant documents are amended and that relevant personnel are made aware of the changed requirements.
Viamed Ltd ISO13485:201 6 7.5.10	Customer property The organization shall identify, verify, protect, and safeguard customer property provided for use or incorporation into the product while it is under the organization's control or being used by the organization. If any customer property is lost, damaged or otherwise found to be unsuitable for use, the organization shall report this to the customer and maintain records (see 4.2.5).
Viamed Ltd ISO13485:201 6 7.5.4	Servicing activities If servicing of the medical device is a specified requirement, the organization shall document servicing procedures, reference materials, and reference measurements, as necessary, for performing servicing activities and verifying that product requirements are met. The organization shall analyse records of servicing activities carried out by the organization or its supplier: a) to determine if the information is to be handled as a complaint; b) as appropriate, for input to the improvement process. Records of servicing activities carried out by the organization or its supplier shall be maintained (see 4.2.5).

Viamed Ltd	Validation of processes for production and service provision	
ISO13485:201	The organization shall validate any processes for production and service provision where	
6 7.5.6	the resulting output cannot be or is not verified by subsequent monitoring or measurement	
	and, as a consequence, deficiencies become apparent only after the product is in use or the	
	service has been delivered.	
	Validation shall demonstrate the ability of these processes to achieve planned results	
	consistently.	
	The organization shall document procedures for validation of processes including:	
	a) defined criteria for review and approval of the processes;	
	b) equipment qualification and qualification of personnel;	
	c) use of specific methods, procedures and acceptance criteria;	
	d) as appropriate, statistical techniques with rationale for sample sizes	
	e) requirements for records (see 4.2.5);	
	f) revalidation, including criteria for revalidation;	
	g) approval of changes to the processes.	
	The organization shall document procedures for the validation of the application of	
	computer software used in production and service provision. Such software applications	
	shall be validated prior to initial use and, as appropriate, after changes to such software or	
	its application. The specific approach and activities associated with software validation	
	and revalidation shall be proportionate to the risk associated with the use of the software	
	including the effect on the ability of the product to conform to specifications.	
	Records of the results and conclusion of validation and necessary actions from the	
	validation shall be maintained (see 4.2.4 and 4.2.5).	
Viamed Ltd	Identification	
ISO13485:201	The organization shall document procedures for product identification and identify	
6 7.5.8	product by suitable means throughout product realization.	
	The organization shall identify product status with respect to monitoring and	
	measurement requirements throughout product realization. Identification of product status	
	shall be maintained throughout production, storage, installation and servicing of product	
	to ensure that only product that has passed the required inspections and tests or released	
	under an authorized concession is dispatched, used or installed.	

If required by applicable regulatory requirements, the organization shall document a

	system to assign unique device identification to the medical device. The organization shall document procedures to ensure that medical devices returned to the organization are identified and distinguished from conforming product.	
Viamed Ltd	Internal audit	
ISO13485:201 6 8.2.4	The organization shall conduct internal audits at planned intervals to determine whether the quality management system:	
0 0.2.4	a) conforms to planned and documented arrangements, requirements of this International	
	Standard, quality management system requirements established by the organization, and applicable regulatory requirements;	
	b) is effectively implemented and maintained.	
	The organization shall document a procedure to describe the responsibilities and	
	requirements for planning and conducting audits and recording and reporting audit results.	
	An audit program shall be planned, taking into consideration the status and importance of	
	the processes and area to be audited, as well as the results of previous audits. The audit	
	criteria, scope, interval and methods shall be defined and recorded (see 4.2.5). The	
	selection of auditors and conduct of audits shall ensure objectivity and impartiality of the	
	audit process. Auditors shall not audit their own work. Records of the audits and their results, including identification of the processes and areas	
	audited and the conclusions, shall be maintained (see 4.2.5).	
	The management responsible for the area being audited shall ensure that any necessary	
	corrections and corrective actions are taken without undue delay to eliminate detected	
	nonconformities and their causes. Follow-up activities shall include the verification of the	
	actions taken and the reporting of verification results.	
	NOTE Further information can be found in ISO 19011.	
Viamed Ltd	Rework	
ISO13485:201	The organization shall perform rework in accordance with documented procedures that	
6 8.3.4	takes into account the potential adverse effect of the rework on the product. These	
	procedures shall undergo the same review and approval as the original procedure.	
	After the completion of rework, product shall be verified to ensure that it meets applicable acceptance criteria and regulatory requirements. Records of rework shall be maintained (see 4.2.5).	

	QUESTION:	RESPONSE:	Y/N
1	Check that out of date warranty repairs have received customer approval prior to any repair work being done.		
2	Verify that goods are identified as a Customer Repair and include a SRN Barcode.		
3	Check that the QA Records - final inspection, test sheets and safety records are completed. Returns – Repairs Ready for Invoice – View Status. Copy the serial number in to serial number search in Stockbook to get the barcode ID. Paste into QA Report. All available reports will be in here.		
4	Check that anti-static precautions are in place and appropriate checks are recorded. Check the workshop, QA and the R+D room. Should these be in place anywhere else around the company.		
5	Check that the correct coloured duckets are being used for Urgent and Export repairs.		
6	Check that the repairs are being worked in priority, and then date order.		
7	Check that completed duckets are placed on the repaired probes shelf with all appropriate paperwork. Check all duckets on the shelves.		
8	Returns – Returns Completed. Pick 5 Invoiced and check the paperwork in the ORD file matches the customer paperwork and the invoice. 1 2 3 4 5		
9	Intrastats Service Logs – are any services overdue, list them. Returns – Service Visits. Look in Notes icon for further info and check any issues attached.		

10	Intrastats Service Logs – are any services in progress.	
	Returns – Service Visits.	
	Check the Notes are they being filled in.	
11	Check round the workshops and make sure all sealant, glues, greases, sprays, tapes and gases are in date and have a data sheet, if no date is present make sure there is a review to check purchase date and lifespan in Intrastats.	
12	Returns – Repairs in building. Pick 5 from the list and go and find them, check they have the appropriate paperwork. 1 2 3 4 5	
13	Check the number of old repairs. Returns – Repairs in building. Find out what is happening with any older than 6 month.	
14	Returns – Ready for quote. Check the 5 oldest from the list and go and find them on the repairs shelf, check they have the appropriate paperwork. 1 2 3 4 5	
15	Returns – Quotes sent. Check the 5 oldest to the Quotes file in the office. Are there notes on intrastats and on the paperwork. 1 2 3 4 5	

16	Returns – Rep[airs Ready for Invoice.	
	Check the oldest 5 of the Viamed / VST SRS's. Why have they not been invoiced.	
	1	
	3	
	4	
	5	
	Using the same 5 copy the Barcode into the QA Report and see if they have QA records.	
17	Returns – Calibration Certificates.	
	From the list click View, to go to the calibration certificate. Copy the serial number in to serial number search in	
	Stockbook to get the barcode ID. Paste into QA Report. Check there is a QA Report is available.	

Sub Processes Linked to Audit 11

Review the below processes tasks and audits and ensure they are completed in a timely manner.

Warehouse Team Leader

Process Scope	Brief Description	Responsibility/Proced ure/Training	Measurable Objective	Task	Audit	Freq	Risk	Overall	Action
6847	Quarantine Repairs	27282 VOP 09 Repairs and Servicing							
6862 - History/Details The repairs that are currently in the building. Confirm the Stage and Location of repairs	Current Repairs	27282 VOP 09 Repairs and Servicing	No repairs should be found in the incorrect location	614 Goods Out	895 Managing Director	4	1	4	Task 1W Audit 3M
7138 - <i>History/Details</i> To review any new QC 21 Forms	Non Conformance Issues Any New QC21 Forms	27178 VOP 13 Process Monitoring, System Reviews, Audits,		795 Managing Director	796 Company Secretary	3	1	3	Task 1M Audit

		Management Review, Analysis Data							12M
7674 - <i>History/Details</i> Review the repairs ready For invoice List in intrastats.	Check Repairs Ready For Invoice List	27282 VOP 09 Repairs and Servicing		468 Goods Out	469 Goods In	4	1	4	Task 2W Audit 3M
7692	Take Complete Repair Paperwork To Office	24730 VOP 03 Contract Review, Enquires, Office Processes							
7905 - History/Details To arrange Supplier Returns Generate RMA box, link items and add faults	Generate RMA Box, Link Items And Add Faults	User Training	Should be no items on the Failed Goods shelf longer than a week	882 Goods In	883 Managing Director	1	1	1	Task 1W Audit 3M

Sales Controller

Process Scope	Brief Description	Responsibility/Proced ure/Training	Measurable Objective	Task	Audit	Freq Risk Overall Action
6916	Service exisiting	24730 VOP 03 Contract Review, Enquires, Office Processes 23395 DO NOT USE VOP 14 Servicing Out of Building Servicing	t			
6917	Service extension	24730 VOP 03 Contract Review, Enquires, Office Processes 23395 DO NOT USE VOP 14 Servicing Out of Building Servicing	t			

Audits

Process Scope	Brief Description	Responsibility/Proced ure/Training	Measurable Objective	Task	Audit	Freq	Risk	Overall	Action
7724 - History/Details To carry out Audit 11 Repairs And Service Viamed	Audit 11 Repairs And Service Viamed	27178 VOP 13 Process Monitoring, System Reviews, Audits, Management Review, Analysis Data			171 Company Secretary	1	2	2	Audit 12M
7772 - History/Details To carry out Audit 11 Repairs And Service VST	Audit 11 Repairs And Service VST	27178 VOP 13 Process Monitoring, System Reviews, Audits, Management Review, Analysis Data			179 Company Secretary	1	2	2	Audit 12M
Repairs Controller									
Process Scope	Brief Description	Responsibility/Proced		Task	Audit	Frea	Risk	Overall	Action
		ure/Training	Objective		ruuri	rrcq	IXISIX	Overan	riction
7823 - History/Details Backup the Fluke ESA61 Safety tester CE	Saftey Tester Data	23322 VOP 11 Equipment Control, Office, Warehouse, Pcs and Equipment	Objective	79	711	1	1	1	Task 12M Audit 12M
Backup the Fluke ESA61	•	23322 VOP 11 Equipment Control, Office, Warehouse, Pcs	Objective	79 Productio n	711 Managing	_			Task 12M Audit
Backup the Fluke ESA61 Safety tester CE Copy any files to the Z Drive - safety tester	•	23322 VOP 11 Equipment Control, Office, Warehouse, Pcs	Objective	79 Productio n	711 Managing	_			Task 12M Audit
Backup the Fluke ESA61 Safety tester CE Copy any files to the Z Drive - safety tester backupdata	•	23322 VOP 11 Equipment Control, Office, Warehouse, Pcs		79 Productio n	711 Managing	1	1		Task 12M Audit 12M

Ensuring customer on site service visits are completed	Logs	Annual Services for Resuscitation Cabinets 24730 VOP 03 Contract Review, Enquires, Office Processes		Office Processes	UK Sales Controller				1W Audit 1M
5879 Goods being returned to usually from customers on our UPS account. We would usually give our account number or send a UPS returns label to them.	_	17155 VM3COP03.05 Procedures for customer returning goods on our UPS account number 23627 VOP 20 Goods in Purchases, Returns, Repairs, Inspection / Rejection	none – this is done on an ad hock basis and only when customers make the request or we feel it is appropriate.			1	1	1	
5898 - History/Details Dispose of depleted oxygen sensors and send customer replacement disposal bags	Processing Depleted Sensors	19667 VM3COP38.14 Depleted Oxygen Sensor Process. VM3COP38.15 Processing Depleted Oxygen Sensors 23627 VOP 20 Goods in Purchases, Returns, Repairs, Inspection / Rejection		406 Goods In	535 Office Processes	4	1	4	Task 2W Audit 2W
7752 - History/Details Ensure all outstanding repairs are being dealt with	SRS Folder	27282 VOP 09 Repairs and Servicing		792 Office Processes	793 Managing Director	3	1	3	Task 1M Audit 3M
7760 - <i>History/Details</i> Send letters to existing customers to remind them that a service is due on	Send Service Offers	24730 VOP 03 Contract Review, Enquires, Office Processes		607 Marketing Processes		1	1	1	Task 1W Audit 4W

their equipment

Goods Out

Process Scope	Brief Description	Responsibility/Proced ure/Training	Measurable Objective	Task	Audit	Freq	Risk	Overall	Action
7690 - History/Details Review the Repairs completed shelf and ship those items that are ready for return to the customer.	Ship Repairs	27282 VOP 09 Repairs and Servicing		492 Goods Out	758 Goods In	5	1	5	Task 1D Audit 1M
7748 - History/Details Check the orders against the customer paperwork, that we have generated, for the repair we have received in.	Check Repair Orders	23373 VOP 22 Picking and Packing Dispatch and Goods Out		575 Goods Out		5	2	10	Task 1D
7749 - History/Details Check the quotes that we send out for the repairs we have received in.	Check Repair Quotes	23373 VOP 22 Picking and Packing Dispatch and Goods Out		576 Goods Out		5	2	10	Task 1D
7906 - History/Details Obtain Returns paperwork / authorisation from supplier to return Items.	Request RMA Based On The RMA Boxes	User Training	RMA unsent List	884 Goods Out		1	1	1	Task 1W