

Work Instructions & Test Methods.

- HTI have there own work instructions as agreed and approved by Viamed
- HTI purchase the components.
- All component changes are agreed with Viamed before incorporation
- The parts are assembled as per the require work instructions
- The completed unit sis tested in line with the IITI in-house designed calibrated equipment
- HTI have a QA procedure for visual Quality.
- Viamed visually QA's to ensure that all labels are in position and that the unit is to the same design.
- The completed unit, is presented to the Q.A. department for assessment. Complete
- Microstims are received having been set up for correct pulse widths and spaces. As these parameters are set by software the units only require a simple go / no-go test as per the Microstim Test & Q.A. procedure VM3COP36.01
- Testing & QA is carried out by suitably familiarised staff.
- If there are any doubts the "Picoscope" is the only Calibration required. There is no set-up required.