

From: Complaints
Sent: 28 January 2021 13:06
To: Owen Wainwright; Mark Radbourne; Hollie Watts; Warehouse
Cc: Rennie Saverton; Simon Motley; Kevin Nash
Subject: (Retunes to Viomed) Multiple Oxygen Sensor Failures ~~CC959~~⁹⁵¹ and CC959

Hi,

Please see below Oxygen Sensor Failures that are required to go back to VIOMED for inspection followed by replacement under warranty .

1. Viomed returns authorisation number **SRS67707** for **CC959 4X** sensor

Three of the sensors are R-47V sensors and their serial numbers are:

- ✓ V104251 (manufactured 2020-03)
- ✓ V104575 (manufactured 2020-10)
- ✓ V104578 (manufactured 2020-10).
- ✓ The fourth sensor is type R22MEDV which is serial number V114652 (manufactured 2020-04).

2. Viomed returns authorisation number **SRS67705** for **CC959 1X** sensor (V115148)

On the address below address:

Viamed Ltd.
15 Station Road
Cross Hills
Keighley
BD20 7DT

+ SRS67707

Did not
receive in
cg 3-2-2021

Kind Reagrds
Ebaa

Ebaa Naji
Quality and Compliance Engineer

Inspiration Healthcare
2 Satellite Business Village, Fleming Way
Crawley, West Sussex, RH10 9NE
W www.inspiration-healthcare.com
T +44 (0)1273 499021
E ebaa.naji@inspiration-healthcare.com

24 hour emergency hire and support call +44 (0) 1455 840 555

Inspiration
HEALTHCARE

