Service Repair Sheet SRS67892

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Fraser Smart

Company/ Hospital Name

Queen Elizabeth University Hospital

Department

Medical Physics

Position

Technician

Direct Phone

01414523782

General Phone

00001853

Opera Account

Email

marcus.stone@ggc.scot.nhs.uk

Order Number

22/Jul/2021

Date Received Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

Notes 12/Jul/2021 Kate Griffiths

12/Jul/2021 Kate Griffiths

Customer to send in V1000 s/n PR02041A10 for annual service.

12/Jul/2021 Kate Griffiths

12/Jul/2021 Kate Griffiths

12/Jul/2021 Kate Griffiths

Customer to send in V1000 s/n PR02041A10 for annual service. Update: delay of a few weeks before the send in as device is needed.

20/Jul/2021 Kate Griffiths

Customer to send in V1000 s/n PR02041A10 for annual service. Customer to send in V1000 s/n PR02041A10 for annual service. Update: delay of a few weeks before the send in as device is needed. UPDATE - device now on its way. 22/Jul/2021 Robert Connor

Received 1 x V1000 s/n PR02041A10, with 4 x AA battery

Ready For quote

CGreen 23-7-7021

Repair Complete Signed

Serial Number Warranty Stock Ref SRN Equipment 1410000 PR02041A10 SRN34017 Foetal Simulator

1480000 × 10 £45 S/N, SRS, SRN

1430309 X1 @ £0 5RS, SRN

UPS × 10 E10



## **DEPARTMENT OF CLINICAL PHYSICS & BIOENGINEERING**

## ITEM FOR REPAIR / SERVICE FORM

| - | CONTRACTOR STATE |
|---|------------------|
|   | 210.             |
|   |                  |

20/07/21

To:

Viamed Ltd.

Address: 15 Station Road

Cross Hills Keighley

West Yorkshire **BD20 7DT** 

United Kingdom

From:

Fraser Smart

Position: Calibration Officer Medical Physics

Address: 2<sup>nd</sup> Floor

Queen Elizabeth University Hospital

1345 Govan Road

Glasgow G51 4TF

Tel:


0141 452 3283


Fax:

Email:

Fraser Smart

| Equipment:                                  | Foetal Heart Simulator                            |   |                                     |  |  |  |
|---|---|---|-------------------------------------|--|--|--|
| Model:                                      | V1000   | Serial No:  | PR02041A10                          |  |  |  |
| Purchase/Acceptance Date:                   |   | Order No:   | SRS67892                            |  |  |  |
| Physics Job No:                             | 3372062   | Contract No:  |                                     |  |  |  |
| REQUEST DETAILS Annual service under retern | number SRS6789                                    | 92  |                                     |  |  |  |
|   | number SRS6789                                    | 92  |                                     |  |  |  |
|   | A QUOTE FOR TH<br>SHOULD BE CAR                   | HE REPAIR OF THE ABOVE                                | IPMENT UNLESS                       |  |  |  |
| Note: PLEASE PROVIDE AND CHARGEABLE WORK S  | A QUOTE FOR TH<br>SHOULD BE CAR<br>EN, USUALLY BY | HE REPAIR OF THE ABOVE RIED OUT ON THIS EQUITOR PURCH | IPMENT UNLESS<br>HASE ORDER NUMBER. |  |  |  |




































meetings opera lookup

producti returns sales

stock stockboo x

## **Select Currency**

Pounds Euros Usd

Repair SRS67892 Values in Pounds @ �1: �1.00

| SRN34017 | Foetal Simulator | 1410000   |          |                |                   |
|----------|------------------|-----------|----------|----------------|-------------------|
|          | Parts Required   | Reference | Quantity | Unit Cost      | <b>Total Line</b> |
|          |                  | 1480000   | 1        | <b>4</b> 5.00  | <b>4</b> 5.00     |
|          |                  | 1430309   | 1        | <b>♦</b> 15.00 | <b>15.00</b>      |
|          |                  |           |          | Parts Cost     | <b>6</b> 60.00    |

toc.

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent