

Residual Risks

The main residual risks remain:-

Sharp edges, Wrong sizes Damage causing cracks in the plastic to harbour bacteria, Build up of CO2

Assessed:- J.S.lamb

Date: - 2011