

Apgar Timer Residual Risk Report

The unit is to be used in the resuscitation cabinet and 100% Oxygen is fed into the Cabinet from wall outlets .This creates a risk if Oxygen leaks whilst the unit is with the cabinet door is closed and the battery overheats

There is a possible risk of time not in sync with other visible clocks in the room causing confusion

Battery could be flat

J.S.Lamb
02/22/11