



VIAMED

Viamed Limited
15 Station Road, Cross Hills, Keighley
West Yorkshire, BD20 7DT, U.K.
Tel: +44 (0)1535 634542
Fax: +44 (0)1535 635582
Email: info@viamed.co.uk
Website: www.viamed.co.uk

MaxO2+ Spare Parts

Reference	Description
0110427	Maxtec Oxygen Sensor MAX-250+
0110429	Maxtec Oxygen Sensor MAX-250E
0110430	Maxtec Oxygen Sensor MAX-250ESF
0110452	Maxtec Oxygen Sensor MAX-550E with standard flow diverter
0120095	Oxygen Sensor Flow Diverter 15 mm
0120120	Oxygen Concentrator Adapter
0120399	`T` adapter. 22mm I.D. - 22mm O.D. Reusable (non-autoclavable) Pack of 5
0121180	`V` Wall Mount
0121182	`V` Mount Pole Clamp - Large Clamping width: 16 - 40 mm
0121300	Lanyard for use with Maxtec MaxO2
0121302	`V` Mount Assembly for use with Maxtec MAXO2
0121318	Maxtec Remote Power Supply, including UK USA EU AUS power adapters
0131604	Coiled cable for MaxO2 - Standard version 3m (10ft) extended, 0.9m (3ft) coiled
0131605	Coiled cable for MaxO2 - Short version 30cm (12") shorter than standard version
0131607	`V` Mount Assembly for use with MaxO2
0131700	Oxygen Sensor Cable Black for use with MaxO2 ME Coiled cable with straight connectors, extendable to 10ft
0131600	Gasket for MaxO2
0131601	Pan Head Screw
0131602	Front Panel Assembly for MaxO2
0131603	Rear Assembly for MaxO2
0131606	Overlay for MaxO2
0131701	Maxtec MaxO2 ME Kick Stand
0191215	MaxO2 A and MaxO2 AE Instructions for use
R228P12	PSU Input Cover
R228P13	Sensor Input Connector
R228P19	Foam Case Tape - Inside of Battery Door
R228P22	Foam Case Tape for Sound Emitter
R228P52	Battery Door Screw
RP06P51	Case Screw Cover
RP06P52	Case Screw
RP59P18	Battery Contacts - Left
RP59P19	Battery Contacts - Right
0131702	Maxtec MaxO2 ME Battery Cover