

AML
Microstim
Battery door ok on sample
Cable I/P ok
Knob welded
Internal clips to be shaved slightly one week delay
Screen print to be straitened
Photo taken
Battery Polarity OK thicken wall to prevent user abuse risk assessment
Nigel must test in OR cleaning cycles
Neck strap thread ok
Packaging Ok
Need standard for barcode
Remove CMDCAS
One serial No from PCB to unit to box
Transformed lot coded
Dot shows 100 tested
EN 60940 for print
Need PÔ FOR SPARE inner packaging
Insurance agreement
Agreement on SpO2 with AML and future way forward.
Separate marketing from manufacturing
Need to know production run
Minimum quantities of each type
Send Liming email on Lightman Envitec prices of SpO2 PCB
AML NEED MARKET needs quantities and prices