

		Reference				New	Repair		Code	(H:M)
SRN35101	Vandagraph Tek Ox	7910211	 1389536	TX3142	Oxygen Analyser Tek-Ox	No	No	Complete - Repaired	Not Switching On	00:30
SRN35101 Engineer Notes: INTERNAL NOTES not for customer discussion 12/Jul/2022 Michael Green The Tek-Ox analyser has been repaired. Some internal contacts have been cleaned.										

Currently Viewing ITEM SRN35101 Vandagraph Tek Ox 7910211 TX3142 Oxygen Analyser Tek-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been repaired. Some internal contacts have been cleaned.	12/Jul/2022 Michael Green The Tek-Ox analyser has been repaired. Some internal contacts have been cleaned.	The Tek-Ox analyser has been repaired. Some internal contacts have been cleaned.

-