

# Viamed Returns Shipping Invoice

Delivery Address:  
Teledyne Analytical Instruments  
Cynar Magno  
16830 Chestnut Street  
City Of Industry  
Germany  
91748-1020  
0016269341589

Date: 28 Mar 2025  
RMA:  
Viamed RN: RTS11001025

Shipper Address:  
Viamed  
15 Station Road  
Cross Hills  
Keighley  
West Yorkshire  
BD20 7DT  
+44 (0) 1535 634542  
+44 (0) 1535 635582  
info@viamed.co.uk

---

Part Number	P/N / Value	Description	Quantity
C43690-R17A-LV	0110107 (\$16.00)	Automotive Oxygen Sensor R-17A	57
	Tariff Code: HTS Code 9027.10.2000		
	Country of Origin: USA		
C43690-R17AH	0110137 (\$33.00)	Automotive Oxygen Sensor R-17A	11
	Tariff Code: HTS Code 9027.10.2000		
	Country of Origin: USA		

Part Number	Serial Number	RMA	Fault Description
C43690-R17A-LV	244800		Output ( 7mv - 11.5mv) 12.2 m Failed in Q.A. Did not reach end user
C43690-R17A-LV	244801		Output ( 7mv - 11.5mv) 12.3 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244802		Output ( 7mv - 11.5mv) 12.1 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244803		Output ( 7mv - 11.5mv) 12.5 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244804		Output ( 7mv - 11.5mv) 11.6 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244805		Output ( 7mv - 11.5mv) 12.4 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244807		Output ( 7mv - 11.5mv) 11.8 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244808		Output ( 7mv - 11.5mv) 12.3 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244809		Output ( 7mv - 11.5mv) 12.2 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244810		Output ( 7mv - 11.5mv) 12.5 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244812		Output ( 7mv - 11.5mv) 12.1 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244813		Output ( 7mv - 11.5mv) 12.3 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244814		Output ( 7mv - 11.5mv) 12.2 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244815		Output ( 7mv - 11.5mv) 12.4mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244816		Output ( 7mv - 11.5mv) 11.9 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244819		Output ( 7mv - 11.5mv) 12.0 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244820		Output ( 7mv - 11.5mv) 12.0 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244821		Output ( 7mv - 11.5mv) 12.2 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244824		Output ( 7mv - 11.5mv) 12.1 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244825		Output ( 7mv - 11.5mv) 12.4 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244826		Output ( 7mv - 11.5mv) 11.4 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244828		Output ( 7mv - 11.5mv) 12.4 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244829		Output ( 7mv - 11.5mv) 12.3 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244830		Output ( 7mv - 11.5mv) 12.0 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244832		Output ( 7mv - 11.5mv) 11.9 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244834		Output ( 7mv - 11.5mv) 11..8 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244835		Output ( 7mv - 11.5mv) 12.5 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244836		Output ( 7mv - 11.5mv) 12.3 mV Failed in Q.A. Did not reach end user

Part Number	Serial Number	RMA	Fault Description
C43690-R17A-LV	244838		Output ( 7mv - 11.5mv) 12.2 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244839		Output ( 7mv - 11.5mv) 12.8mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244840		Output ( 7mv - 11.5mv) 12.9 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244841		Output ( 7mv - 11.5mv) 12.1 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244842		Output ( 7mv - 11.5mv) 12.3 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244843		Output ( 7mv - 11.5mv) 12.2mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244844		Output ( 7mv - 11.5mv) 11.6 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244845		Output ( 7mv - 11.5mv) 11.9 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244846		Output ( 7mv - 11.5mv) 11.7 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244847		Output ( 7mv - 11.5mv) 12.6 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244848		Output ( 7mv - 11.5mv) 12.9 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244849		Output ( 7mv - 11.5mv) 12.4 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244851		Output ( 7mv - 11.5mv) 12.5 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244852		Output ( 7mv - 11.5mv) 11.8 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244856		Output ( 7mv - 11.5mv) 12.4 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244857		Output ( 7mv - 11.5mv) 12.2 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244858		Output ( 7mv - 11.5mv) 12.4 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244859		Output ( 7mv - 11.5mv) 12.5 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244863		Output ( 7mv - 11.5mv) 12.3 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244864		Output ( 7mv - 11.5mv) 11.9 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244865		Output ( 7mv - 11.5mv) 12.2mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244866		Output ( 7mv - 11.5mv) 11.9 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244867		Output ( 7mv - 11.5mv) 12.5 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244869		Output ( 7mv - 11.5mv) 12.3 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244870		Output ( 7mv - 11.5mv) 12.1 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244871		Output ( 7mv - 11.5mv) 11.7 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244872		Output ( 7mv - 11.5mv) 12.7 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244873		Output ( 7mv - 11.5mv) 12.4 mV Failed in Q.A. Did not reach end user
C43690-R17A-LV	244874		Output ( 7mv - 11.5mv) 12.3 mV Failed in Q.A. Did not reach end user
C43690-R17AH	244707		Output ( 10.5mV - 13.5mV ) 13.7mV Failed in Q.A. Did not reach end user

Part Number	Serial Number	RMA	Fault Description
C43690-R17AH	244709		Output ( 10.5mV - 13.5mV ) 14.8 mV Failed in Q.A. Did not reach end user
C43690-R17AH	244711		Output ( 10.5mV - 13.5mV ) 14.3 mV Failed in Q.A. Did not reach end user
C43690-R17AH	244714		Output ( 10.5mV - 13.5mV ) 14.3 mV Failed in Q.A. Did not reach end user
C43690-R17AH	244719		Output ( 10.5mV - 13.5mV ) 14.0 mV Failed in Q.A. Did not reach end user
C43690-R17AH	244731		Failed in QA did not reach end user
C43690-R17AH	244732		Output ( 10.5mV - 13.5mV ) 14.1 mV Failed in Q.A. Did not reach end user
C43690-R17AH	244743		Output ( 10.5mV - 13.5mV ) 14.3 mV Failed in Q.A. Did not reach end user
C43690-R17AH	244750		Output ( 10.5mV - 13.5mV ) 14.2 mV Failed in Q.A. Did not reach end user
C43690-R17AH	244760		Output ( 10.5mV - 13.5mV ) 13.7 mV Failed in Q.A. Did not reach end user
C43690-R17AH	244764		Output ( 10.5mV - 13.5mV ) 13.7 mV Failed in Q.A. Did not reach end user