

Viamed Returns Shipping Invoice

Delivery Address:
Teledyne Analytical Instruments
Repairs
16830 Chestnut Street
City Of Industry
California
91748-1017

Date: 31 Mar 2026
RMA:
Viamed RN: RTS11001077

Shipper Address:
Viamed
15 Station Road
Cross Hills
Keighley
West Yorkshire
BD20 7DT
+44 (0) 1535 634542
+44 (0) 1535 635582
info@viamed.co.uk

Returns Under Warranty Value for Customs : \$100.00
See Attached Listing for Serial numbers and Faults

Part Number	P/N / Value	Description	Quantity
0110121	0110121 (\$20.00 ea) Tariff Code: HTS Code 9027.10.2000 Country of Origin: USA	Oxygen sensor - Automotive R-	27

Part Number	Serial Number	RMA	Fault Description
0110121	326764		Output 9mV - 14mV 14.6mV Failed in Q.A. Did not reach end user
0110121	326772		Output 9mV - 14mV 14.9 mV Failed in Q.A. Did not reach end user
0110121	326796		Output 9mV - 14mV 15.3 mV Failed in Q.A. Did not reach end user
0110121	326820		Output 9mV - 14mV 15.8 mV Failed in Q.A. Did not reach end user
0110121	326832		Output 9mV - 14mV 15.0 mV Failed in Q.A. Did not reach end user
0110121	326835		Output 9mV - 14mV 15.4 mV Failed in Q.A. Did not reach end user
0110121	326859		Output 9mV - 14mV 15.5 mV Failed in Q.A. Did not reach end user
0110121	326890		Output 9mV - 14mV Failed in Q.A. Did not reach end user
0110121	326902		Output 9mV - 14mV 15.2 Failed in Q.A. Did not reach end user
0110121	340468		Output 9mV - 14mV 14.5 14.6mV Failed in Q.A. Did not reach end user
0110121	340476		Output 9mV - 14mV 0.15-13.2 erratic Failed in Q.A. Did not reach end user
0110121	340480		Output 9mV - 14mV 15.2 mV Failed in Q.A. Did not reach end user
0110121	340486		Output 9mV - 14mV 15.4 mV Failed in Q.A. Did not reach end user
0110121	340491		Output 9mV - 14mV 14.9mV Failed in Q.A. Did not reach end user
0110121	340498		Output 9mV - 14mV 15.0 mV Failed in Q.A. Did not reach end user
0110121	340500		Output 9mV - 14mV 16.1 mV Failed in Q.A. Did not reach end user
0110121	340519		Output 9mV - 14mV 14.5 mV Failed in Q.A. Did not reach end user
0110121	340536		Output 9mV - 14mV 14.3 mV Failed in Q.A. Did not reach end user
0110121	340555		Output 9mV - 14mV 12.9 14.3mV Failed in Q.A. Did not reach end user
0110121	340559		Output 9mV - 14mV 15.2 mV Failed in Q.A. Did not reach end user
0110121	340564		Output 9mV - 14mV 14.3 mV Failed in Q.A. Did not reach end user
0110121	340580		Output 9mV - 14mV 0.01 mV Failed in Q.A. Did not reach end user
0110121	340587		Output 9mV - 14mV 14.9 mV Failed in Q.A. Did not reach end user
0110121	340591		Output 9mV - 14mV 14.2 mV Failed in Q.A. Did not reach end user
0110121	340596		Output 9mV - 14mV 14.3 mV Failed in Q.A. Did not reach end user
0110121	340600		Output 9mV - 14mV 14.9 mV Failed in Q.A. Did not reach end user
0110121	340602		Output 9mV - 14mV 15.2 mV Failed in Q.A. Did not reach end user

Part Number	Serial No.	RMA	Fault Report
0110121	326764		
0110121	326772		
0110121	326796		
0110121	326820		
0110121	326832		
0110121	326835		
0110121	326859		
0110121	326890		
0110121	326902		
0110121	340468		
0110121	340476		
0110121	340480		
0110121	340486		
0110121	340491		
0110121	340498		
0110121	340500		
0110121	340519		
0110121	340536		
0110121	340555		
0110121	340559		
0110121	340564		
0110121	340580		
0110121	340587		
0110121	340591		
0110121	340596		
0110121	340600		
0110121	340602		