

Viamed Returns Shipping Invoice

Delivery Address:
Teledyne Analytical Instruments
Warranty Returns
16830 Chestnut Street
City Of Industry
California
91748-1017

Date: 26 May 2026
RMA: 0063294
Viamed RN: RTS11001081

Shipper Address:
Viamed
15 Station Road
Cross Hills
Keighley
West Yorkshire
BD20 7DT
+44 (0) 1535 634542
+44 (0) 1535 635582
info@viamed.co.uk

Returns Under Warranty Value for Customs : \$1296.00
See Attached Listing for Serial numbers and Faults

| Part Number | P/N / Value | Description | Quantity |
|-------------|---|--------------------------------|----------|
| C43690-R17A | 0110117 (\$27.00) Tariff Code: HTS Code 9027.10.2000 Country of Origin: USA | Automotive Oxygen Sensor R-17A | 48 |

| Part Number | Serial Number | RMA | Fault Description |
|-------------|---------------|---------|--|
| C43690-R17A | 220810 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220811 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220812 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220813 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220814 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220815 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220816 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220817 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220818 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220819 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220820 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220821 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220822 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220823 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220824 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220825 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220826 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220827 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220828 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |
| C43690-R17A | 220830 | 0063294 | Unacceptable date of manufacture Country of Origin: USA Customs Value \$27.00 each |

| Part Number | Serial No. | RMA | Fault Report |
|-------------|------------|---------|--------------|
| C43690-R17A | 179191 | 0063294 | |
| C43690-R17A | 179192 | 0063294 | |
| C43690-R17A | 179193 | 0063294 | |
| C43690-R17A | 179194 | 0063294 | |
| C43690-R17A | 179195 | 0063294 | |
| C43690-R17A | 181786 | 0063294 | |
| C43690-R17A | 181787 | 0063294 | |
| C43690-R17A | 181788 | 0063294 | |
| C43690-R17A | 181791 | 0063294 | |
| C43690-R17A | 181792 | 0063294 | |
| C43690-R17A | 181793 | 0063294 | |
| C43690-R17A | 181794 | 0063294 | |
| C43690-R17A | 181795 | 0063294 | |
| C43690-R17A | 181796 | 0063294 | |
| C43690-R17A | 181797 | 0063294 | |
| C43690-R17A | 181798 | 0063294 | |
| C43690-R17A | 181799 | 0063294 | |
| C43690-R17A | 220799 | 0063294 | |
| C43690-R17A | 220800 | 0063294 | |
| C43690-R17A | 220801 | 0063294 | |
| C43690-R17A | 220802 | 0063294 | |
| C43690-R17A | 220803 | 0063294 | |
| C43690-R17A | 220804 | 0063294 | |
| C43690-R17A | 220805 | 0063294 | |
| C43690-R17A | 220806 | 0063294 | |
| C43690-R17A | 220807 | 0063294 | |
| C43690-R17A | 220808 | 0063294 | |
| C43690-R17A | 220809 | 0063294 | |
| C43690-R17A | 220810 | 0063294 | |
| C43690-R17A | 220811 | 0063294 | |
| C43690-R17A | 220812 | 0063294 | |
| C43690-R17A | 220813 | 0063294 | |
| C43690-R17A | 220814 | 0063294 | |
| C43690-R17A | 220815 | 0063294 | |

| Part Number | Serial No. | RMA | Fault Report |
|-------------|------------|---------|--------------|
| C43690-R17A | 220816 | 0063294 | |
| C43690-R17A | 220817 | 0063294 | |
| C43690-R17A | 220818 | 0063294 | |
| C43690-R17A | 220819 | 0063294 | |
| C43690-R17A | 220820 | 0063294 | |
| C43690-R17A | 220821 | 0063294 | |
| C43690-R17A | 220822 | 0063294 | |
| C43690-R17A | 220823 | 0063294 | |
| C43690-R17A | 220824 | 0063294 | |
| C43690-R17A | 220825 | 0063294 | |
| C43690-R17A | 220826 | 0063294 | |
| C43690-R17A | 220827 | 0063294 | |
| C43690-R17A | 220828 | 0063294 | |
| C43690-R17A | 220830 | 0063294 | |