



Viamed Production Sheet PS3821

U Drive: WVM3821.pdf

Advanced Ref 1754392433

Started:05/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By _____

Boxed By _____



Barcode(2797226) PR03821A10 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797227) PR03821A11 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797228) PR03821A12 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797229) PR03821A13 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797230) PR03821A14 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797231) PR03821A15 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797232) PR03821A16 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797233) PR03821A17 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797234) PR03821A18 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797235) PR03821A19 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797236) PR03821A20 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797237) PR03821A21 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797238) PR03821A22 Produced [] Q.A. [] Boxed Ready For Sale []





Viamed Production Sheet PS3821

U Drive: WVM3821.pdf

Advanced Ref 1754392433

Started:05/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By _____

Boxed By _____



Barcode(2797239) PR03821A23 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797240) PR03821A24 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797241) PR03821A25 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797242) PR03821A26 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797243) PR03821A27 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797244) PR03821A28 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797245) PR03821A29 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797246) PR03821A30 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797247) PR03821A31 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797248) PR03821A32 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797249) PR03821A33 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797250) PR03821A34 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797250) PR03821A34 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797251) PR03821A35 Produced [] Q.A. [] Boxed Ready For Sale []



Viamed Production Sheet PS3821

U Drive: WVM3821.pdf

Advanced Ref 1754392433

Started:05/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By _____

Boxed By _____



Barcode(2797252) PR03821A36 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797253) PR03821A37 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797254) PR03821A38 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797255) PR03821A39 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797256) PR03821A40 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797257) PR03821A41 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797258) PR03821A42 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797259) PR03821A43 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797260) PR03821A44 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797261) PR03821A45 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797262) PR03821A46 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797263) PR03821A47 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797264) PR03821A48 Produced [] Q.A. [] Boxed Ready For Sale []



Viamed Production Sheet PS3821

U Drive: WVM3821.pdf

Advanced Ref 1754392433

Started:05/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By _____

Boxed By _____



Barcode(2797265) PR03821A49 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797266) PR03821A50 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797267) PR03821A51 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797268) PR03821A52 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797269) PR03821A53 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797270) PR03821A54 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797271) PR03821A55 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797272) PR03821A56 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797273) PR03821A57 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797274) PR03821A58 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797275) PR03821A59 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797276) PR03821A60 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797277) PR03821A61 Produced [] Q.A. [] Boxed Ready For Sale []





Viamed Production Sheet PS3821

U Drive: WVM3821.pdf

Advanced Ref 1754392433

Started:05/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By _____

Boxed By _____



Barcode(2797278) PR03821A62 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797279) PR03821A63 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797280) PR03821A64 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797281) PR03821A65 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797282) PR03821A66 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797283) PR03821A67 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797284) PR03821A68 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797285) PR03821A69 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797286) PR03821A70 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797287) PR03821A71 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797288) PR03821A72 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797289) PR03821A73 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797290) PR03821A74 Produced [] Q.A. [] Boxed Ready For Sale []



Viamed Production Sheet PS3821

U Drive: WVM3821.pdf

Advanced Ref 1754392433

Started:05/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By _____

Boxed By _____



Barcode(2797291) PR03821A75 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797292) PR03821A76 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797293) PR03821A77 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797294) PR03821A78 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797295) PR03821A79 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797296) PR03821A80 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797297) PR03821A81 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797298) PR03821A82 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797299) PR03821A83 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797300) PR03821A84 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797301) PR03821A85 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797302) PR03821A86 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797303) PR03821A87 Produced [] Q.A. [] Boxed Ready For Sale []





Viamed Production Sheet PS3821

U Drive: WVM3821.pdf

Advanced Ref 1754392433

Started:05/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By _____

Boxed By _____



Barcode(2797304) PR03821A88 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797305) PR03821A89 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797306) PR03821A90 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797307) PR03821A91 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797308) PR03821A92 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797309) PR03821A93 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797310) PR03821A94 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797311) PR03821A95 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797312) PR03821A96 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797313) PR03821A97 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797314) PR03821A98 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797315) PR03821A99 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797316) PR03821A100 Produced [] Q.A. [] Boxed Ready For Sale []



Viamed Production Sheet PS3821

U Drive: WVM3821.pdf

Advanced Ref 1754392433

Started:05/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By _____

Boxed By _____



Barcode(2797317) PR03821A101 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797318) PR03821A102 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797319) PR03821A103 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797320) PR03821A104 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797321) PR03821A105 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797322) PR03821A106 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797323) PR03821A107 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797324) PR03821A108 Produced [] Q.A. [] Boxed Ready For Sale []



Barcode(2797325) PR03821A109 Produced [] Q.A. [] Boxed Ready For Sale []