



# Viamed Production Sheet PS3822

U Drive: WVM3822.pdf

Advanced Ref 1755875813

Started:22/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_



Barcode(2807927) PR03822A10 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807928) PR03822A11 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807929) PR03822A12 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807930) PR03822A13 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807931) PR03822A14 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807932) PR03822A15 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807933) PR03822A16 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807934) PR03822A17 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807935) PR03822A18 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807936) PR03822A19 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807937) PR03822A20 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807938) PR03822A21 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807939) PR03822A22 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3822

U Drive: WVM3822.pdf  
Advanced Ref 1755875813  
Started:22/Aug/2025 By Catherine Spence Quantity 100  
8000054 Cable assembly for oxygen sensor 8010004  
Produced By Michael Green  
Q.A. By \_\_\_\_\_  
Boxed By \_\_\_\_\_

-  Barcode(2807940) PR03822A23 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2807941) PR03822A24 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2807942) PR03822A25 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2807943) PR03822A26 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2807944) PR03822A27 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2807945) PR03822A28 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2807946) PR03822A29 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2807947) PR03822A30 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2807948) PR03822A31 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2807949) PR03822A32 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2807950) PR03822A33 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2807951) PR03822A34 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2807952) PR03822A35 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3822

U Drive: WVM3822.pdf

Advanced Ref 1755875813

Started:22/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_



Barcode(2807953) PR03822A36 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807954) PR03822A37 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807955) PR03822A38 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807956) PR03822A39 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807957) PR03822A40 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807958) PR03822A41 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807959) PR03822A42 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807960) PR03822A43 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807961) PR03822A44 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807962) PR03822A45 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807963) PR03822A46 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807964) PR03822A47 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807965) PR03822A48 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3822

U Drive: WVM3822.pdf

Advanced Ref 1755875813

Started:22/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_



Barcode(2807966) PR03822A49 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807967) PR03822A50 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807968) PR03822A51 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807969) PR03822A52 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807970) PR03822A53 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807971) PR03822A54 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807972) PR03822A55 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807973) PR03822A56 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807974) PR03822A57 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807975) PR03822A58 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807976) PR03822A59 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807977) PR03822A60 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807978) PR03822A61 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3822

U Drive: WVM3822.pdf

Advanced Ref 1755875813

Started:22/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_



Barcode(2807979) PR03822A62 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807980) PR03822A63 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807981) PR03822A64 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807982) PR03822A65 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807983) PR03822A66 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807984) PR03822A67 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807985) PR03822A68 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807986) PR03822A69 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807987) PR03822A70 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807988) PR03822A71 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807989) PR03822A72 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807990) PR03822A73 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2807991) PR03822A74 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3822

U Drive: WVM3822.pdf

Advanced Ref 1755875813


Started:22/Aug/2025 By Catherine Spence Quantity 100


8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2807992) PR03822A75 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2807993) PR03822A76 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2807994) PR03822A77 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2807995) PR03822A78 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2807996) PR03822A79 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2807997) PR03822A80 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]


 Barcode(2807998) PR03822A81 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]


 Barcode(2807999) PR03822A82 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2808000) PR03822A83 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2808001) PR03822A84 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2808002) PR03822A85 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2808003) PR03822A86 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2808004) PR03822A87 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3822

U Drive: WVM3822.pdf

Advanced Ref 1755875813














Started:22/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

-  Barcode(2808005) PR03822A88 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2808006) PR03822A89 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2808007) PR03822A90 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2808008) PR03822A91 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2808009) PR03822A92 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2808010) PR03822A93 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2808011) PR03822A94 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2808012) PR03822A95 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2808013) PR03822A96 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2808014) PR03822A97 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2808015) PR03822A98 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2808016) PR03822A99 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]
-  Barcode(2808017) PR03822A100 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3822

U Drive: WVM3822.pdf

Advanced Ref 1755875813

Started:22/Aug/2025 By Catherine Spence Quantity 100

8000054 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_



Barcode(2808018) PR03822A101 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2808019) PR03822A102 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2808020) PR03822A103 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2808021) PR03822A104 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2808022) PR03822A105 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2808023) PR03822A106 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2808024) PR03822A107 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2808025) PR03822A108 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2808026) PR03822A109 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]