



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2874705) PR03881A10 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874706) PR03881A11 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874707) PR03881A12 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874708) PR03881A13 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874709) PR03881A14 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874710) PR03881A15 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874711) PR03881A16 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874712) PR03881A17 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874713) PR03881A18 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874714) PR03881A19 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874715) PR03881A20 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874716) PR03881A21 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874717) PR03881A22 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2874718) PR03881A23 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874719) PR03881A24 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874720) PR03881A25 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874721) PR03881A26 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874722) PR03881A27 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874723) PR03881A28 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874724) PR03881A29 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874725) PR03881A30 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874726) PR03881A31 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874727) PR03881A32 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874728) PR03881A33 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874729) PR03881A34 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874730) PR03881A35 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2874731) PR03881A36 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874732) PR03881A37 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874733) PR03881A38 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874734) PR03881A39 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874735) PR03881A40 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874736) PR03881A41 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874737) PR03881A42 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874738) PR03881A43 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874739) PR03881A44 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874740) PR03881A45 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874741) PR03881A46 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874742) PR03881A47 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874743) PR03881A48 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2874744) PR03881A49 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874745) PR03881A50 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874746) PR03881A51 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874747) PR03881A52 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874748) PR03881A53 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874749) PR03881A54 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874750) PR03881A55 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874751) PR03881A56 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874752) PR03881A57 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874753) PR03881A58 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874754) PR03881A59 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874755) PR03881A60 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874756) PR03881A61 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2874757) PR03881A62 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874758) PR03881A63 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874759) PR03881A64 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874760) PR03881A65 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874761) PR03881A66 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874762) PR03881A67 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874763) PR03881A68 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874764) PR03881A69 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874765) PR03881A70 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874766) PR03881A71 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874767) PR03881A72 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874768) PR03881A73 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874769) PR03881A74 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2874770) PR03881A75 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874771) PR03881A76 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874772) PR03881A77 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874773) PR03881A78 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874774) PR03881A79 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874775) PR03881A80 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874776) PR03881A81 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874777) PR03881A82 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874778) PR03881A83 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874779) PR03881A84 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874780) PR03881A85 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874781) PR03881A86 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874782) PR03881A87 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_



Barcode(2874783) PR03881A88 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874784) PR03881A89 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874785) PR03881A90 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874786) PR03881A91 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874787) PR03881A92 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874788) PR03881A93 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874789) PR03881A94 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874790) PR03881A95 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874791) PR03881A96 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874792) PR03881A97 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874793) PR03881A98 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874794) PR03881A99 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874795) PR03881A100 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2874796) PR03881A101 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874797) PR03881A102 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874798) PR03881A103 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874799) PR03881A104 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874800) PR03881A105 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874801) PR03881A106 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874802) PR03881A107 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874803) PR03881A108 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874804) PR03881A109 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874805) PR03881A110 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874806) PR03881A111 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874807) PR03881A112 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874808) PR03881A113 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2874809) PR03881A114 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874810) PR03881A115 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874811) PR03881A116 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874812) PR03881A117 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874813) PR03881A118 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874814) PR03881A119 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874815) PR03881A120 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874816) PR03881A121 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874817) PR03881A122 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874818) PR03881A123 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874819) PR03881A124 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874820) PR03881A125 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874821) PR03881A126 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_



Barcode(2874822) PR03881A127 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874823) PR03881A128 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874824) PR03881A129 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874825) PR03881A130 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874826) PR03881A131 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874827) PR03881A132 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874828) PR03881A133 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874829) PR03881A134 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874830) PR03881A135 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874831) PR03881A136 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874832) PR03881A137 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874833) PR03881A138 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874834) PR03881A139 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2874835) PR03881A140 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874836) PR03881A141 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874837) PR03881A142 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874838) PR03881A143 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874839) PR03881A144 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874840) PR03881A145 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874841) PR03881A146 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874842) PR03881A147 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874843) PR03881A148 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874844) PR03881A149 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874845) PR03881A150 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874846) PR03881A151 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874847) PR03881A152 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2874848) PR03881A153 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874849) PR03881A154 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874850) PR03881A155 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874851) PR03881A156 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874852) PR03881A157 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874853) PR03881A158 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874854) PR03881A159 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874855) PR03881A160 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874856) PR03881A161 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874857) PR03881A162 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874858) PR03881A163 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874859) PR03881A164 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874860) PR03881A165 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2874861) PR03881A166 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874862) PR03881A167 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874863) PR03881A168 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874864) PR03881A169 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874865) PR03881A170 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874866) PR03881A171 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874867) PR03881A172 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874868) PR03881A173 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874869) PR03881A174 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874870) PR03881A175 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874871) PR03881A176 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874872) PR03881A177 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874873) PR03881A178 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2874874) PR03881A179 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874875) PR03881A180 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874876) PR03881A181 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874877) PR03881A182 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874878) PR03881A183 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874879) PR03881A184 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874880) PR03881A185 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874881) PR03881A186 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874882) PR03881A187 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874883) PR03881A188 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874884) PR03881A189 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874885) PR03881A190 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874886) PR03881A191 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_

 Barcode(2874887) PR03881A192 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874888) PR03881A193 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874889) PR03881A194 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874890) PR03881A195 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874891) PR03881A196 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874892) PR03881A197 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874893) PR03881A198 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874894) PR03881A199 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874895) PR03881A200 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874896) PR03881A201 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874897) PR03881A202 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874898) PR03881A203 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]

 Barcode(2874899) PR03881A204 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



# Viamed Production Sheet PS3881

U Drive: WVM3881.pdf

Advanced Ref 1769525642

Started:27/Jan/2026 By Catherine Spence Quantity 200

8000004 Cable assembly for oxygen sensor 8010004

Produced By Michael Green

Q.A. By \_\_\_\_\_

Boxed By \_\_\_\_\_



Barcode(2874900) PR03881A205 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874901) PR03881A206 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874902) PR03881A207 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874903) PR03881A208 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]



Barcode(2874904) PR03881A209 Produced [ ] Q.A. [ ] Boxed Ready For Sale [ ]