

Calibration Index

Outstanding as @ 01/08/2019

KEY

Calibration DUE
Previously Calibrated Externally
Previously Calibrated Internally
Inactive /Removed from service
Indication Only
Type not set

Equipment	Barcode ID	CE Number	Serial Number	Last Updated	Next Due	Location	status	Internal Cal With (Barcode)	Request Calibration
Calibrate	1303764	CE208	Unknown	Jan/1970	Jan/1970				Request Calibration

All Known Equipment :

Equipment	Barcode ID	CE Number	Serial Number	Last Updated	Next Due	Location	status	Internal Cal With (Barcode)	Request Calibration
Calibrate	Hameg Oscilloscope	101686	CE002	06744	Jul/2010	Before Use	Main Office SpO2 Q.A. Shelf	Indication	
Calibrate	Hameg Oscilloscope	101987	CE003	3729	Jun/2007	Before Use	Main Office	Indication	
Calibrate	Microcal	101988	CE004	2845e2	Sep/2016	Oct/2015		Removed From Service	102060
Calibrate	T1 And T2 Tester	101989	CE005	Unknown	Sep/2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication	
Calibrate	R22 Tester/R24	101990	CE006	Unknown	Jul/2010	Jul/2012	Main Office White Rack	Removed From Service	102060
Calibrate	Maxtec Max 02	101991	CE007	JK12399012	Jul/2007	Before Use	Main Office	Indication	
Calibrate	Digimatic	101992	CE008	Unknown	Sep/	Before	Main		

	Micrometer				2006 Use		Office	
Calibrate	BS 3849 Guages	101993	CE009	Unknown	Sep/2006	Before Use	Main Office	Indication
Calibrate	BS 3849 Guages	101994	CE010	Unknown	Sep/2006	Before Use	Main Office	Indication
Calibrate	BS 3849 Guages	101995	CE011	Unknown	Sep/2006	Before Use		Indication
Calibrate	TED200/T7 Tester	101996	CE012	Unknown	Jun/2007	Before Use	Main Office White Rack	Indication
Calibrate	Oxycal	101997	CE013	Unknown	Sep/2006	May/2007		Inactive
Calibrate	OxyDig	101998	CE014	117	Sep/2006	Before Use	Main Office	Indication
Calibrate	Euromedical ECG simulator	101999	CE015	1018	Sep/2006	Before Use	Main Office	Inactive
Calibrate	Nellcor NPB-190 spo2	102000	CE016	21648435	Sep/2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication
Calibrate	Nellcor NBP-290 spo2	102001	CE017	21664706	Sep/2006	Before Use		Indication
Calibrate	Fluke DVM	102002	CE018	3486920	Aug/2011	Before Use	Main Office	Indication 102060
Calibrate	Spectrometer Prema 9001	102003	CE019	10030	Nov/2006	Before Use	Main Office	Indication
Calibrate	Picoscope virtual instrument	102004	CE020	SOR34/100	Apr/2007	Before Use	Main Office	Indication
Calibrate	Multimeter M5010	102005	CE021	Unknown	Sep/2006	Before Use		Indication
Calibrate	Multimeter M5050E Analogue	102006	CE022	902830	Sep/2006	Before Use	Main Office	Indication
Calibrate	TED120/ T1 Tester	102007	CE023	60845	Sep/2006	Before Use	Main Office White Rack	Indication
Calibrate	Hudson Sensor Holder Tester	102008	CE024	Unknown	Sep/2006	Before Use		Indication
Calibrate	Hudson 5552	102009	CE025	55527196	Sep/2006	Before Use		Inactive
Calibrate	Teledyne TED80	102010	CE026	50439	Sep/2006	Before Use	Main Office	Indication

Calibrate	T5 T5A simulator	102011	CE027	Unknown	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	ET30/2 P.S.U.	102012	CE028	1198	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	F61 Function Generator	102013	CE029	598	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Function Generator	102014	CE030	4838	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Ohmeda Oxygen Monitor	102015	CE031	FAB200144	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Frequency meter	102016	CE032	4414	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Temperature probe test box	102017	CE033	Unknown	Sep/ 2006	Before Use		Indication
Calibrate	CM2700 DVM	102018	CE034	D19477549	Sep/ 2006	Before Use		Indication
Calibrate	Decade resistance box	102019	CE035	27631	Sep/ 2006	Before Use	Main Office	Inactive
Calibrate	TED60	102020	CE036	Unknown	Sep/ 2006	Before Use		Indication
Calibrate	TED60	102021	CE037	58332	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	S4000 NIBP simulator	102022	CE038	Unknown	Sep/ 2006	Before Use		Indication
Calibrate	Colin BP-408	102023	CE039	0052IE	Feb/ 2011	Before Use	Main Office	Removed From Service
Calibrate	CM2700 DVM	102024	CE040	D19477680	Sep/ 2006	Before Use		Indication
Calibrate	Ventronics 5590 R13 Tester	102025	CE041	5590017366	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Tester Fluke DVM 8000A	102026	CE042	66956	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Megger BM101	102027	CE043	1016 M90056	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Rigel Safety Tester 255	102028	CE044	Unknown	Oct/2008	Jan/1972		Inactive
Calibrate	Ventronics 5577 R13 Tester	102029	CE045	17154	Sep/ 2006	Before Use	Main Office White Rack	Indication
Calibrate	Viamed Transistor Tester	102030	CE046	Unknown	Sep/ 2006	Before Use		Indication
Calibrate	Beckman 785 Breakout Box	102031	CE047	12861402	Sep/ 2006	Before Use		Indication

Calibrate	RS Wristband ESD Checker	102032	CE048	Unknown	Sep/2006	Before Use		Indication	
Calibrate	RS Wristband ESD Checker	102033	CE049	Unknown	Sep/2006	Before Use	Main Office	Indication	
Calibrate	RS ESD Checker	102034	CE050	Unknown	Sep/2006	Before Use		Indication	
Calibrate	Sonicaid FM6 u/sound monitor	102035	CE051	1382B	Sep/2006	Before Use		Indication	
Calibrate	HP 8030A u/sound monitor	102036	CE052	2021G04253	Sep/2006	Before Use	Main Office	Indication	
Calibrate	Ohmeda Spo2 3800	102037	CE053	FBFA04730	Sep/2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication	
Calibrate		102038	CE054	Unknown	Sep/2006	Jan/1970		Inactive	
Calibrate	Multimeter Fluke 77	102039	CE055	39581028	Aug/2018	Sep/2018		Removed From Service	102060
Calibrate	Micro Cal Lost - removed from service	102040	CE056	5431B5	Jul/2009	Before Use		Indication	
Calibrate		102041	CE057	Unknown	Sep/2006	Jan/1970		Inactive	
Calibrate	R23 Tester (1/2)	102042	CE058	50613890	Oct/2018	Oct/2020	Main Office White Rack	Calibrated	102060
Calibrate	R23 Tester (1/2)	102043	CE059	50613891	Dec/2017	Dec/2019	Main Office White Rack	Calibrated	102060
Calibrate	Epic Test Box	102044	CE060	CE060	Sep/2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication	
Calibrate	Component Tester	102045	CE061	1414	Sep/2006	Before Use		Indication	
Calibrate	Wavetek Multimeter	102046	CE062	50613892	Mar/2007	Before Use	Main Office	Removed From Service	
Calibrate	Kontron Spo2	102047	CE063	2282	Sep/2006	Before Use	Main Office SpO2	Indication	

							Q.A. Shelf	
Calibrate	Nellcor Spo2 - Scrapped	102048	CE064	Pb03991081	Sep/ 2007	Before Use		
Calibrate	Palco Spo2	102049	CE065	CE065	Sep/ 2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication
Calibrate	Novametrix Spo2	102050	CE066	66-1065a	Sep/ 2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication
Calibrate	Ohmeda Spo2 3700e	102051	CE067	118-72170	Sep/ 2006	Before Use		Indication
Calibrate	Elmed Spo2	102052	CE068	Ps1020167	Sep/ 2006	Before Use		Indication
Calibrate	Criticare Spo2	102053	CE069	2862908	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Sensor Medics Spo2	102054	CE070	CE070	Sep/ 2006	Before Use		Indication
Calibrate	Simed Spo2	102055	CE071	CE071	Sep/ 2006	Before Use		Indication
Calibrate	Datascope Spo2	102056	CE072	CE072	Sep/ 2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication
Calibrate	Datex Spo2	102057	CE073	CE073	Sep/ 2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication
Calibrate	Physio Control Spo2	102058	CE074	CE074	Sep/ 2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication
Calibrate	Micro Cal	102059	CE075	CE075	Sep/ 2006	Before Use		Indication
Calibrate	Micro Cal	102060	CE076	6839K6	May/ 2019	May/2020	Main Office	Calibrated
Calibrate	Pressure Gauge Digitron 2022P	102061	CE077	010494852	Feb/ 2016	Feb/2017		Removed From Service 102133
Calibrate	Pressure Guage	102062	CE078	04314	Aug/ 2019	May/2020		Calibrated

Calibrate	Flow Meter	102063	CE079	Unknown	Sep/2006	Before Use	Main Test Bench	Indication	
Calibrate	Fluke 867B	102064	CE080	6911002	Oct/2014	Oct/2014	Main Office	Removed From Service	
Calibrate		102065	CE081	Unknown	Sep/2006	Jan/1970		Inactive	
Calibrate	DMM CM2700 R15/R23	102066	CE082	Unknown	Oct/2018	Oct/2020	Main Office White Rack	Calibrated	102060
Calibrate	MCI Pulse Oximeter	102067	CE083	170276631	Sep/2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication	
Calibrate	Oxyshuttle	102068	CE084	1825	Sep/2006	Before Use		Indication	
Calibrate	CSI Criticare	102069	CE085	291 108486	Sep/2006	Before Use		Indication	
Calibrate	Mennen Mercury	102070	CE086	B1017	Sep/2006	Before Use	Main Office	Indication	
Calibrate	Oxycal	102071	CE087	Unknown	Jul/2010	May/2008	Main Office White Rack	Removed From Service	
Calibrate	Oxycal	102072	CE088	Unknown	Jul/2010	May/2008		Removed From Service	
Calibrate	Oxycal	102073	CE089	Unknown	Sep/2006	Before Use	Main Office White Rack	Indication	
Calibrate	DMM CM2700	102074	CE090	Unknown	Jan/2016	Before Use		Indication	102060
Calibrate	Pres Guage Digitron P200L	102075	CE091	10198	May/2019	May/2020	Main Test Bench	Calibrated	
Calibrate	DL30 Light Source	102076	CE092	Unknown	Sep/2006	Before Use		Indication	
Calibrate	DL300 Probe Calibrator	102077	CE093	Unknown	Jun/2007	Before Use	Main Office	Calibrated	
Calibrate	Caltek DMM CM9700	102078	CE094	E19563280	Sep/2006	Before Use	Main Office	Indication	
Calibrate	DL3000 Spo2 Simulator	102079	CE095	8J0103	Aug/2018	Before Use	Main Office SpO2 Q.A. Shelf	Removed From Service	

Calibrate	Caltek DMM CM1200A	102080	CE096	D19456321	Feb/ 2013	Before Use		Removed From Service	
Calibrate	Caltek DMM CM1200A	102081	CE097	D19456325	Sep/ 2006	Before Use		Indication	
Calibrate	Caltek DMM CM1200A	102082	CE098	D19456337	Sep/ 2012	Before Use		Indication	
Calibrate	Fluke DMM 77	102083	CE099	39321066	Aug/ 2011	Before Use	Main Office	Indication	102060
Calibrate	Micro Cal	102084	CE100	8580B0	Oct/2 014	Before Use	Main Office	Inactive	102060
Calibrate	Nonin oximeter 8500	102085	CE101	HH14662	Sep/ 2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication	
Calibrate	Comdek oximeter	102086	CE102	5628	Sep/ 2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication	
Calibrate	Simed S100 oximeter	102087	CE103	50505	Sep/ 2006	Before Use		Indication	
Calibrate	Ohmeda 5100 oxygen monitor	102088	CE104	AALM02799	Sep/ 2006	Before Use	Main Office	Indication	
Calibrate	Ohmeda 5100 oxygen monitor	102089	CE105	AALN03730	Sep/ 2006	Before Use	Main Office	Indication	
Calibrate	cm2700	102090	CE106	19562915	Sep/ 2006	Before Use	Main Office	Indication	
Calibrate	DVM CM2700 CalTek	102091	CE107	19563160	Mar/ 2016	Before Use	Main Office	Indication	102060
Calibrate	Ventronics 5524	102092	CE108	12210	Sep/ 2006	Before Use	Main Office	Indication	
Calibrate	Caltek CM1200A	102093	CE109	D19477293	Sep/ 2006	Before Use		Indication	
Calibrate	Caltek CM1200A	102094	CE110	D19477292	Sep/ 2016	Sep/201 8	Main Office White Rack	Removed From Service	102060
Calibrate	Caltek CM1200A	102095	CE111	D19477299	Oct/2 018	Oct/202 0	Main Office White Rack	Calibrated	102060
Calibrate	Caltek CM1200A	102096	CE112	D19477379	Oct/2 012	Before Use		Indication	102060

Calibrate	Calktek CM1200A	102097	CE113	D19477322	Sep/ 2006	Before Use		Indication
Calibrate	Calktek CM1200A	102098	CE114	D19477312	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Calktek CM1200A	102099	CE115	D19477294	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	EP613 PSU	102100	CE116	61337129	Sep/ 2006	Before Use		Indication
Calibrate	Ohmeda 3700e oximeter	102101	CE117	FMAW00870	Sep/ 2006	Before Use		Indication
Calibrate	HP 78354A spO2	102102	CE118	2934G10841	Sep/ 2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication
Calibrate	Palco Spo2	102103	CE119	3340-0474	Sep/ 2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication
Calibrate	Ohmeda 3740 SpO2	102104	CE120	FMQU02760	Sep/ 2006	Before Use		Indication
Calibrate	Nellcor NP- 40 SpO2	102105	CE121	G01848910	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	DL3000	102106	CE122	OD030	Sep/ 2006	Before Use		Indication
Calibrate	Torque wrench	102107	CE123	4684	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Torque wrench	102108	CE124	1930006641	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	ECG Simulator	102109	CE125	Unknown	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Digital Vernier	102110	CE126	Unknown	Sep/ 2006	Before Use	Main Office	Indication
Calibrate		102111	CE127	Unknown	Sep/ 2006	Before Use	Main Office	Inactive
Calibrate	Libra Temp monitor	102112	CE128	LMB 342182	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	DL3000	102113	CE129	Unknown	Sep/ 2006	Before Use		Indication
Calibrate	Flow Meter	102114	CE130	Unknown	Sep/ 2006	Before Use	Main Test Bench	Indication
Calibrate	Calktek CM1200A	102115	CE131	B19145783	Sep/ 2006	Before Use		Indication
Calibrate	CSI Criticare 504 SpO2	102116	CE132	293172483	Sep/ 2006	Before Use	Main Office SpO2	Indication

							Q.A. Shelf	
Calibrate	Massimo Radical	102117	CE133	107477	Sep/ 2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication
Calibrate	Mennen ECG Simulator	102118	CE134	B0473	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Mennen ECG Simulator	102119	CE135	B0472	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Defibrillator Tester	102120	CE136	1/86054	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Soldering Iron	102121	CE137	Unknown	Sep/ 2006	Before Use		Indication
Calibrate	Seaward PrimeTest100 PAT Tester	102122	CE138	Z28-0458	Mar/ 2018	Mar/2020		Calibrated
Calibrate	Soldering Iron	102123	CE139	Unknown	Sep/ 2006	Before Use		Indication
Calibrate	Soldering Iron	102124	CE140	Unknown	Sep/ 2006	Before Use		Indication
Calibrate	Soldering Iron	102125	CE141	Unknown	Sep/ 2006	Before Use		Indication
Calibrate	Soldering Iron	102126	CE142	Unknown	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Soldering Iron	102127	CE143	Unknown	Sep/ 2006	Before Use		Indication
Calibrate	Soldering Iron	102128	CE144	Unknown	Sep/ 2006	Before Use		Indication
Calibrate	Hameg Component Tester	102129	CE145	4414	Sep/ 2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication
Calibrate	Soldering Iron Tester	102130	CE146	53124498	Jul/2010	Before Use		
Calibrate	Soldering Iron Calibrator	102131	CE147	53118199	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	Soldering Iron	102132	CE148	Unknown	Sep/ 2006	Before Use	Main Office Row 9 Block 1 Shelf 5	Indication
Calibrate	Digitron Manometer	102133	CE149	420720660	Aug/ 2019	May/2020	Main Test Bench	Calibrated
Calibrate	Criticare	102134	CE150	H3159	Sep/	Before	Main	Indication

	Dinamap SpO2				2006	Use	Office SpO2 Q.A. Shelf	
Calibrate	Novametrix 515A SpO2	102135	CE151	69-2479BC	Sep/2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication
Calibrate	Datascope Accusta SpO2	102136	CE152	6351-A9	Sep/2006	Before Use		Indication
Calibrate	CSI Criticare 508 SpO2	102137	CE153	492159808	Sep/2006	Before Use		Indication
Calibrate	Drager Baby Lung	102138	CE154	Unknown	Aug/2007	Before Use	Main Office Row 2 Block 1 Shelf 1 - Demo	Indication
Calibrate	MX300I	102139	CE155	328802	Sep/2006	Before Use	Main Office	Indication
Calibrate	TED6oT	102140	CE156	160656	Sep/2006	Before Use	Main Office	Indication
Calibrate	Ohmeda 5120	102141	CE157	650135	Sep/2006	Before Use	Main Office	Indication
Calibrate	Oxydig	102142	CE158	7949	Sep/2006	Before Use	Main Office	Indication
Calibrate	Hudson	102143	CE159	Unknown	Sep/2006	Before Use	Main Office	Indication
Calibrate	DM900	102144	CE160	LMB4D052	Sep/2006	Before Use	Main Office	Indication
Calibrate	TED160	102145	CE161	68858	Sep/2006	Before Use	Main Office	Indication
Calibrate	Pressure Guage	102146	CE162	Unknown	Sep/2006	Before Use	Main Office	Indication
Calibrate	Calteck CS10H Oscilloscope	102147	CE163	2041010	Sep/2006	Before Use	Main Office	Indication
Calibrate	Microcal 1030	102148	CE164	1212E06	Mar/2011	Sep/2008	Main Office	Removed From Service
Calibrate	Small Scales	102149	CE165	4049882	Sep/2011	Before Use	Main Office Bookcase 1 Shelf 10	Indication
Calibrate	Scales DS20L	102150	CE166	N/A	Sep/2011	Before Use	Main Office	Indication

							Bookcase 1 Shelf 10	
Calibrate	Nellcor PT2500	102151	CE167	B08787	Sep/ 2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication
Calibrate	Component Tester	102152	CE168	n/a	Sep/ 2006	Before Use	Main Office SpO2 Q.A. Shelf	Indication
Calibrate	Fluke 187 DVM	102153	CE169	N/K	Dec/ 2017	Dec/201 9		Calibrated 102060
Calibrate	DM900	102154	CE170	LMB4D055	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	TC100 Temperature Calibrator	102155	CE171	JFEL7101	Sep/ 2006	Before Use	Main Office	Indication
Calibrate	VG900	121321	CE172	CK62504956	Jan/2 007	Before Use		Indication
Calibrate	Hulme Martin model 900S	128365	CE173	9/1702	Feb/ 2007	Before Use		Indication
Calibrate		130008	-	Unknown	Oct/2 012	Jan/1970		Removed From Service
Calibrate	ADC-24 Pico	406730	CE174	ZNR2850	Jan/2 015	Before Use	Main Being Booked in	Indication
Calibrate	Tenma Thermometer	418957	CE175	1100081011	Oct/2 012	Sep/201 1	Main Being Booked in	Removed From Service
Calibrate	Tenma Thermometer	418958	CE176	1100080993	Oct/2 012	Sep/201 1	Main Being Booked in	Removed From Service
Calibrate	Sadaat Masimo	463000	CE177	Unknown	Jun/2 015	Before Use	Main Being Booked in	Indication
Calibrate	Pressure Gauge Digitron P200UL	674700	CE178	530569434	Aug/ 2019	Aug/202 0		Calibrated 102133
Calibrate	DVM 187 Fluke	682836	CE0179	76950984	Dec/ 2017	Dec/201 9	Main Being	Calibrated 102060

							Booked in	
Calibrate	DVM rapitest DM25	682937	CE0180	07010046459	Jan/2018	Jan/2020	Main Being Booked in	Calibrated 102060
Calibrate	Blue Point Flow Sensor tester	689559	CE0181	ID689559	Jan/2018	Feb/2020	R & D Room	Calibrated
Calibrate	Fluke Pat Tester ESA615	697263	CE182	2433026	Mar/2019	Mar/2020		Calibrated
Calibrate		803009	CE183	Unknown	Oct/2014	Jan/1970		Removed From Service
Calibrate	TF930 Frequency Generator	843663	CE0185	425571	Jun/2019	Jun/2020	Main Being Booked in	Calibrated
Calibrate	Oscilloscope	844778	CE186	C013518	May/2017	Before Use	Main Office Q.A. Back Shelf	Indication
Calibrate	Cable tester	850209	CE187	Unknown	Aug/2016	Before Use		Indication
Calibrate	Old Microstim Tester	995716	CE192	Unknown	Aug/2018	Sep/2020		Indication
Calibrate	Cable tester	995709	CE188	Unknown	Aug/2018	Sep/2020	Main Office Q.A. Back Shelf	Indication
Calibrate	DB3 Tester	995710	CE189	Unknown	Aug/2018	Sep/2020	Main Office Q.A. Back Shelf	Indication
Calibrate	DB3 Tester	995711	CE190	Unknown	Aug/2016	Sep/2018	Main Office Q.A. Back Shelf	Removed From Service
Calibrate	R17 Oxycal	995712	CE191	Unknown	Aug/2018	Sep/2020	Main Office Q.A. Back Shelf	Indication

Calibrate	JCCR - cable tester	996362	CE196	Unknown	Aug/2018	Sep/2020		Indication
Calibrate	MX300i	996363	CE193	295487	Aug/2018	Sep/2020		Indication
Calibrate	VM2160-L	996364	CE194	00000286	Aug/2018	Sep/2020		Indication
Calibrate	Jack Plug Tester	996365	CE195	Unknown	Aug/2018	Sep/2020		Indication
Calibrate		996367	CE196	Unknown	Aug/2018	Sep/2018		Removed From Service
Calibrate	Oxugen Monitor	996378	CE197	295495	Aug/2018	Sep/2020	Main Being Booked in	Indication
Calibrate	Oxygen Monitor	996379	CE198	264339	Aug/2018	Sep/2020	Main Being Booked in	Indication
Calibrate	Saadat monitor	996380	CE199	Unknown	Aug/2018	Sep/2018	Main Being Booked in	Removed From Service
Calibrate	Pulse Oximeter	1049900	CE200	Unknown	Mar/2018	Feb/2018		Inactive
Calibrate	S063	1089943	CE201	000178	Jul/2018	Jun/2018	Main Office Row 9 Block 1 Shelf 5	Removed From Service
Calibrate	Servicing Tool Case - Needs checking	1194723	CE202	Unknown	Oct/2018	Oct/2019		Calibrated
Calibrate	DVM Linked to PI auto tester	1245756	CE203	CE203	Aug/2018	Sep/2019		Calibrated 102060
Calibrate		1265355	CE204	Unknown	Jul/2018	Jan/1970		Removed From Service
Calibrate		1265356	CE205	Unknown	Jul/2018	Jan/1970		Removed From Service
Calibrate	DVM	1288063	CE206	3027310	Aug/2018	Sep/2019		Calibrated 102060
Calibrate	Oxygen monitor	1303613	CE207	BM82699024	Oct/2018	Oct/2019		Calibrated
Calibrate		1303764	CE208	Unknown	Jan/1970	Jan/1970		

