

<u>ENGLISH</u>	<u>TURKISH</u>	<u>CORRECT TURKISH</u>
PROBE OFF	MİL KAPALI	SENSÖR ÇIKTI
Probe off	Mil kapalı	Sensör çıktı
(This is correct in the manual, not on the device; I do not know what does “Mil Kapalı” means, it does not make any sense)		
SpO2 Averaging		
STABLE	SAĞLAM	HAREKETSİZ
Stable	Sağlam	Hareketsiz