

Wed Meeting 24/5/23
all present

New format meeting

SH - Did Emtec training on
manitors both buildings
did posing training too.

added to training manager
if update training Reg reading -

MLF19 + MLF19 GE
same but has removable flow
diverter.

customers using original Flow
diverter on new sensors.

don't know if our Flow diverter
will work.

sensor compatible - just Flow
diverters.

SN
look at getting some?

don't know if GE add them or
if Gambert do.

'does ^{add} not include Flow Diverter'

'has M16 upst thread but
not come with GE Flow
Diverter'

Issue - 296007