

AM Full, SN Full



SINGLE ITEM 8010004 - VST - Returns Statistics 2024-01-22

Get Data

Export CSV

Start From	22/01/2022
------------	------------

End at 22/01/2024

Honeywell Healthcare Solutions GmbH

 CID5922 Opera VST0004 Type:Company Supplier

Honeywell Healthcare Solutions GmbH Alter

Holzhafen 18, Wismar, , D-23966, Germany

Tel **0049 3841 360204** Distributor Euro (0004)



Add Issue

Credit Credit Limit 0.00EUR

VAT DE137437213

 Account Home

 Main Details

Account Memos

 Sales History

Purchase Orders

Stock References

 Cust./Supp. Returns



Service Visits

Distributor Agreements

Documents
Files

 **Linked Issues**

Regulatory Agreements

SINGLE ITEM 8010004 - VST

Unique Faults QA , Demo & Customer 22 Jan 2022 - 23 Jan 2024

	Cleaned Fault	8010004
Super Clean	Electrolyte Leakage	1
Super Clean	High Output	3
Super Clean	Linearity Error	2
Super Clean	Low Output	6
Super Clean	No Output	14
Super Clean	Unstable Output Signal	39
Super Clean	Zero Offset Signal Out Of Tolerance	1

Months to Failure From Invoice Customers

22 Jan 2022 - 23 Jan 2024

	From Invoice to Customer to Booked into Returns system (Customers)												
Clean Code	1	2	3	4	5	6	7	8	9	10	11	12	13
	Months	Months	Months	Months	Months	Months	Months	Months	Months	Months	Months	Months	Months
Unstable Output Signal		1	4	4	8	4	4	4	5	2	1		1

22/01/2024, 12:32

Stock Group Returns

High Output	1			1				1					
Zero Offset Signal Out Of Tolerance								1					
No Output 1	3	1	1				1	2	1	2	1		
Linearity Error			1	1									
Low Output	1	1						2	1	1			
Electrolyte Leakage								1					

Stock References Months to Failure From Invoice Customers 22 Jan 2022 - 23 Jan 2024

From Invoice to Customer to Booked into Returns system (Customers)													
Reference	1 Months	2 Months	3 Months	4 Months	5 Months	6 Months	7 Months	8 Months	9 Months	10 Months	11 Months	12 Months	13 Months
8010004	1	2	9	5	10	6	4	6	11	4	4	1	1

Break Down Parts To Fault Code

Stock Ref	Supplier Ref	Description	Fault Code	Cleaned Fault Code	True Fault?	Qty
8010004	8010004	E1001721, OOD103-2V Oxygen Sensor	Electrolyte Leakage	Electrolyte Leakage	Fault	1
8010004	8010004	E1001721, OOD103-2V Oxygen Sensor	High Output	High Output	Fault	3
8010004	8010004	E1001721, OOD103-2V Oxygen Sensor	Linearity Error	Linearity Error	Fault	2
8010004	8010004	E1001721, OOD103-2V Oxygen Sensor	Low Output	Low Output	Fault	6
8010004	8010004	E1001721, OOD103-2V Oxygen Sensor	No Fault Found	No Fault Found	No Fault	19
8010004	8010004	E1001721, OOD103-2V Oxygen Sensor	No Output	No Output	Fault	14
8010004	8010004	E1001721, OOD103-2V Oxygen Sensor	Out Of Warranty	Out Of Warranty	No Fault	1
8010004	8010004	E1001721, OOD103-2V Oxygen Sensor	Unstable Output Signal	Unstable Output Signal	Fault	39
8010004	8010004	E1001721, OOD103-2V Oxygen Sensor	Zero Offset Signal Out Of Tolerance	Zero Offset Signal Out Of Tolerance	Fault	1