



# VIAMED

## Oxygen Analysers



### Handi+

This analyser is great for spot-checking oxygen percentage in hospitals, clinics and in homecare environments. Includes integrated sensor and battery.

- One-touch calibration
- Auto-off (after 80 seconds)
- Response time: <15 seconds to 90% of value
- Disposable at end of sensor life
- Overmould for extra protection



### UltraMax

The UltraMaxO<sub>2</sub> offers a fast and easy verification of oxygen concentration, flow and outlet pressure of oxygen concentrators

- Accurately measure oxygen, flow & pressure
- No oxygen sensor required
- No in-field calibration
- Self-diagnostics
- Shielded, reinforced sample gas inlet port
- Measuring range: 20.9 - 96.0%

# MaxO<sub>2</sub>+A & MaxO<sub>2</sub>+AE

The MaxO<sub>2</sub>+A analyser is ideal for checking oxygen percent accuracy in concentrators.

With the same specification as the MaxO<sub>2</sub>+A, the MaxO<sub>2</sub>+AE is best used anywhere an inline analyser is needed, when alarms are not deemed important. It is especially useful in conjunction with older ventilators or oscillators.

- Long battery life (approximately 5,000 hours on 2 x AA batteries)
- Impact resistant and drip proof
- Ergonomical handheld design
- Large LCD with 3.5 digit display



## MaxO<sub>2</sub> ME

The MaxO<sub>2</sub> ME low-maintenance oxygen monitor with smart alarms auto-set at 3% ± current reading

- Long battery life (approximately 5,000 hours on 2 x AA batteries)
- Back lit LCD display
- Adjustable alarms from 15 - 99%
- DC power port (power supply sold separately)
- Smart alarms
- Protective overmould
- Sets alarms 3% ± current reading
- Built-in kickstand and dove tail

For a copy of our full Oxygen Monitoring Catalogue  
go to our website

[https://www.viamed.co.uk/  
oxygenmonitoringcatalogue](https://www.viamed.co.uk/oxygenmonitoringcatalogue)

+44 (0)1535 634542  
[www.viamed.co.uk](http://www.viamed.co.uk)