



Sedana

16  
Mail

Compose

Back Archive Spam Delete Mark as unread Move to Inbox More

Thanks again Bernd, understood and agreed.

## Inbox

16

Steve

Chat

Snoozed

Sent

On Thu, 15 May 2025 at 17:50, Lindner, Bernd <[b.lindner@bluepoint-medical.com](mailto:b.lindner@bluepoint-medical.com)> wrote:

Meet

Categories

155

Hello Steve,

Social

1,897

the connectors are standard connectors and used also at gas sampling lines from Dräger, GE,

Updates

1

The IFU is absolutely clear and also labelling.

Forums

1

With best regards

Promotions

251

Bernd

More

## Labels

## LAMB

Patent Lawer

**Von:** Steve Nixon <[steve.nixon@viamed.co.uk](mailto:steve.nixon@viamed.co.uk)>**Gesendet:** Donnerstag, 15. Mai 2025 18:43:05**An:** Lindner, Bernd**Cc:** Boetcher, Uwe; Froehlich, Heidi; Wigger, D.; Derek Lamb; Ryan Swaine**Betreff:** Customer complaint - Gas Sampling Line H 8090121313V - Maidstone hospital

## WORK

Customer complaint - Gas Sampling Line H 8090121313V

More

Dear Bernd

Please see below and the attached regarding details of the compliant. Viamed and Sedana believe that the sampling

Are you in agreement?

**Nature of Complaint:** Maidstone Hospital (UK) reported that the gas sampling line looks too similar to a feed line which could cause a problem if they are connected up incorrectly.

Sedana have requested some of the feed lines to investigate this matter.

Upgrade

