



John Lamb <viamed.john.lamb@gmail.com>

Customer problem

2 messages

John Lamb <john.lamb@vandagraph.co.uk>
To: Jerry Whatley <info@custombreathers.com>
Bcc: Valeriy Gorbunov <vgorbuno@yahoo.com>

Sun, Oct 6, 2013 at 12:07 PM

Hi Jerry,

I have recently received an email from one of your customers. I have replied that I can discuss his problem in general terms how sensors react in rebreathers but not discuss specifically Megladon.
I have advised him to contact you direct.

Meanwhile I will be examining the data he sent me and will reply to him.
As I need to protect his/her confidentiality here is a precis of my reply to him/her

Hi

I am out of the office for a few days and need to examine your data closely before I can reply in depth..
Meanwhile two important things.

1. It is vital you copy your email to Jerry Whately at InnerSpace.

I cannot comment on the Megladon without Jerry being aware and contributing.

As John Lamb I have had experience with oxygen sensors since 1965 and with their use in re-breathers since 1995. I can therefore discuss in depth my experiences and how sensors work and generally re-act underwater.

For legal reasons any specific comments on InnerSpace sensors has to be routed through them. I see no problems in this area.

2. Have you read my book "The practice of oxygen measurement for divers"

Did you by any chance measure the sensor outputs in air when they were new?
What are they now? Are atmospheric conditions similar.

Kind regards
John S. Lamb

info@custombreathers.com <info@custombreathers.com>
To: John Lamb <john.lamb@vandagraph.co.uk>

Mon, Oct 7, 2013 at 9:48 PM

Hi John,

Thanks, can you share with me what the customers problem was?

Best,

Jerry

From: viamed.john.lamb@gmail.com [mailto:viamed.john.lamb@gmail.com] **On Behalf Of** John Lamb
Sent: Sunday, October 06, 2013 4:07 AM
To: Jerry Whatley
Subject: Customer problem

[Quoted text hidden]

This message has been scanned for malware.