



Jan Grzywna

 CID22010 Opera CID22010 Type:Vandagraph Retail

Jan Grzywna 15 Hillpark Ave, Hoghton, nr. Preston, , PR5 0AS,

Tel **07944 152733** GBP Retail Price List Vandagraph (0010)

Proforma Credit Limit 0.00GBP

 Log Call

 Account Home

 Main Details

Account Memos

Sales History

Stock References

🔄 Cust./Supp. Returns



Service Visits

Distributor Agreements

Documents
Files

 Linked Issues

Regulatory Agreements

SRS68299

SRS Created : 26 Sep 2022

Created By Ryan Swaine

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

Handle with care

Add Items to Supplier Returns Box

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

--	--

Add Notes

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Service Repair Sheet 68299		Notes
Company / Hospital	Jan Grzywna	26/Sep/2022 Ryan Swaine
Contact Name	Jan Grzywna	26/Sep/2022 Ryan Swaine
Department		Analox O2 Ell, has had a new battery and sensor, but the connector appears to be corroded and needs replacing.
Position		28/Sep/2022 Robert Connor
Company Phone	07944 152733	Unknown device sent, no s/n.
Direct Phone	07944 152733	
Opera Account	CID22010	LINKED ISSUE NOTES:
Email	jan@jgcontrols.co.uk	274526: AutoGenerated Issue SRS68299 Appears to be Complete
Order Number		
Viamed ORD Number		17 Oct 2022 Catherine Spence vandagraph repair
Date Received Into building	28 Sep 2022	274527: AutoGenerated Issue SRS68299 Appears to be Complete
Type	Quote Before Repair	
Issues?	274526 274527	17 Oct 2022 Catherine Spence vandagraph repair

Items for Repair

SRN	Equipment	Stock	Barcode	Serialnumber	Description	Warranty	Warranty	Status	Repair	Time
-----	-----------	-------	---------	--------------	-------------	----------	----------	--------	--------	------

		Reference				New	Repair		Code	(H:M)
SRN35472	Plastic Products				Analox	No	No	Complete - Repaired 13 Oct 2022 Michael Green	No Reading	01:00
SRN35472 Engineer Notes: INTERNAL NOTES not for customer discussion 13/Oct/2022 Michael Green The Analox monitor has been repaired. The corroded sensor wire has been replaced.										

Currently Viewing ITEM SRN35472 Plastic Products Analox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Analox monitor has been repaired. The corroded sensor wire has been replaced.	13/Oct/2022 Michael Green The Analox monitor has been repaired. The corroded sensor wire has been replaced.	The Analox monitor has been repaired. The corroded sensor wire has been replaced.

1