



Bavaria Blue for Safari

 CID**9556** Opera **BAVARIA** Type:**Vandagraph Trade**
Bavaria Blue for Safari 3 Royal Mews, Chilwell, Nottingham, , NG9
 5FZ, UK
 Tel **0115 9431430** GBP Trade Price List Vandagraph (0009)

 Proforma Credit Limit 0.00GBP

```

graph LR
    A[Account Home] --> B[Main Details]
    B --> C[Account Memos]
    C --> D[Sales History]
    D --> E[Stock References]
    E --> F[Cust./Supp. Returns]
    F --> G[Service Visits]
    G --> H[Distributor Agreements]
    I[Documents Files] --> B
    J[Linked Issues] --> C
    K[Regulatory Agreements] --> D
  
```

spoke to paul re payment hes in eygpt until monday 10th january, will pay then for repair

SRS68310

SRS Created : 13 Oct 2022
Created By Ryan Swaine

[Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)

Handle with care
Add Items to Supplier Returns Box

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68310		Notes
Company / Hospital	Bavaria Blue for Safari	13/Oct/2022 Ryan Swaine
Contact Name	Paul Cooper	13/Oct/2022 Ryan Swaine
Department		TEK-OX giving E1 Error, to repair and return to customer before 24/10/22. Please let RS as soon as it arrives.
Position		
Company Phone	0115 9431430	18/Oct/2022 Robert Connor
Direct Phone	0115 943 1430	Received 1 x tek-ox s/n 0933
Opera Account	BAVARIA	
Email	pscroyal@outlook.com	<i>LINKED ISSUE NOTES:</i>
Order Number		274908 :
Viamed ORD Number		Added by Robert Connor sent to Ryan Swaine
Date Received Into building	18 Oct 2022	INFORMATION ONLY ISSUE DO NOT ADD NOTES!
Type	Repair Approved	SRS68310 has arrived, 1 x tek-ox s/n 0933, I've put it up in the vandagraph room on the big desk.
Issues?	274908 275065 275066	275065 :
		AutoGenerated Issue SRS68310 Appears to be Complete
		275066 :
		AutoGenerated Issue SRS68310 Appears to be Complete

Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN35481	Oxygen Analyser TEK-OX	9710203	 407675	0933	Oxygen Analyser TEK-OX	No	No	Complete - Repaired 19 Oct 2022 Michael Green	E1	02:00
SRN35481 Engineer Notes: INTERNAL NOTES not for customer discussion 19/Oct/2022 Michael Green The TEK-OX analyser has been repaired. The PCB, calibration pot, front case panel and battery door have been replaced.										

Currently Viewing ITEM SRN35481 Oxygen Analyser TEK-OX 9710203 0933 Oxygen Analyser TEK-OX

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The TEK-OX analyser has been repaired. The PCB, calibration pot, front case panel and battery door have been replaced.	19/Oct/2022 Michael Green The TEK-OX analyser has been repaired. The PCB, calibration pot, front case panel and battery door have been replaced.	The TEK-OX analyser has been repaired. The PCB, calibration pot, front case panel and battery door have been replaced.