

Service Repair Sheet SRS68308

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Andrew Kelly
Whiston Hospital
Medical Engineering
Senior Medical Engineer / Deputy
0151 430 1273
01514261600
00002152
Andrew.Kelly@sthk.nhs.uk

17/Oct/2022
Robert Connor
Viamed
Warranty

VIAMEDclean	
Goods In Only	
Decontamination certificate provided by customer	<input type="checkbox"/>
Cleaned by Viamed, if no declaration certificate from customer	<input type="checkbox"/>
Signed: _____	
Date: _____	
Goods Out Only	
Cleaned by Viamed before returning to customer	
Signed: _____	
Date: _____	

Notes 12/Oct/2022 Steve Hardaker

12/Oct/2022 Steve Hardaker

Returning a pair of R22Vi (Sr/no V105444 & V105445) which are failing calibration in an Isolette 8000 incubator. He says they are reading 12mv & 11.5mv respectively. Still under warranty.

13/Oct/2022 Steve Hardaker

He advised these failed due to too large a differential between the sensors. He tried closer matched ones and they worked fine.

17/Oct/2022 Robert Connor

Received 2 x R22Vi s/n V105444, V105445.

Ready For quote

Repair Complete Signed

CCGreen 19.10.22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35479	Oxygen Sensor	0110072	V105444 / V105445	Yes

0140013 x 1 FOC
Old SIN'S, SRS, SRN

0110072 x 1 FOC
New SIN'S SRS, SRN

UPS x 1 FOC

UPS x 1 FOC

UPS x 1 FOC

St Helens and Knowsley Teaching Hospitals **NHS**
University Clinical Education Centre

Medical Engineering,
Whiston Hospital,
Prescot,
Merseyside,
L35 5DR

0151 430 1273
andrew.kelly@sthk.nhs.uk

12/10/2022

Viamed Limited,
15 Station Road,
Cross Hills,
Keighley,
West Yorkshire,
BD20 7DT

REF: SRS68308.

Dear Sir / Madam,

Please find enclosed a matched pair of Viamed R-22Vi (sr/no V105444 & V105445). The cells were manufactured in DEC '21 and have failed. I would like to return them under warranty for replacement as discussed with Steve Hardaker.

Regards,

Andrew Kelly
(Deputy Manager Medical Engineering)

Service Repair Sheet 68308

Contact Name

Andrew Kelly

Company/ Hospital Name

Whiston Hospital

Department

Medical Engineering

Position

Senior Medical Engineer / Deputy Manager

Direct Phone

0151 430 1273

General Phone

01514261600

Opera Account

00002152

Email

Andrew.Kelly@sthk.nhs.uk

Date Received

17/Oct/2022

Booked in By

Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35479	0110072	V105444 / V105445	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110072

Both replaced as a pair under warranty with S/N V106017/ V106018.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35482	0110072	V105445	Oxygen Sensor	

Time :0 Hour(s)
