

# Service Repair Sheet SRS68304

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Purchasing

Eden Medical (UK) Ltd

01314406500

0131 440 6500

00012178

info@edenmedical.co.uk

12/Oct/2022

Robert Connor

Viamed

Quote

## VIAMEDclean

### Goods In Only

Decontamination  
certificate provided  
by customer ☐

Cleaned by Viamed,  
if no declaration certificate  
from customer ☐

Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

### Goods Out Only

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

Notes 10/Oct/2022 Steve Nixon

10/Oct/2022 Steve Nixon

Returning VM-2500S for assessment and quote. Comes up with occlusion alarm even when used with new airway adapter 4420531 and VersaStream sampling line 4420825.

Can't determine whether they purchased NOMO adapter during initial ownership and from Intrastats they have only used 125 lines and adapters over approx. 3 years.

12/Oct/2022 Robert Connor

Received 1 x VM2500S s/n 60920171

Ready For quote

CGreen 26.10.22

Repair Complete Signed

CGreen 10.11.22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35476	Capnograph	4410520	60920171	N

4440000 0.5hr @ £90 per hr

S/N, SRS, S/N

4430200 x 1 @ £12.50

SRS, S/N

4430201 x 1 £15.00

SRS, S/N

UPS x 1 @ £12

Service Repair Sheet 68304

Contact Name

Company/ Hospital Name

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Purchasing

Eden Medical (UK) Ltd

01314406500

0131 440 6500

00012178

info@edenmedical.co.uk

AP12222923

12/Oct/2022

Robert Connor

---

Repair	Ref	S/N	Equipment Type
SRN35476	4410520	60920171	Capnograph

Complete - Repaired  
Time :0.5 Hour(s)

Parts Replaced

Qty: 1 4430201

Qty: 1 4430200

Qty: 0.5 4440000

---

The Capnograph VM2500-S has been repaired. The CO2 scrubber and exhaust port top have been replaced.

---

## PURCHASE ORDER: AP12222923

<b>Buyer</b> REGISTERED HEAD OFFICE EGLINTON HOUSE AILSA HOSPITAL AYR, SOUTH AYRSHIRE KA6 6AB	<b>Order Date</b> 4 Nov 2022	<b>Invoice To</b> accountspayable@aapct.scot.nhs.uk ACCOUNTS PAYABLE GREENAN HOUSE AILSA HOSPITAL, AYR KA6 6AB
<b>Supplier</b> VIAMED 15 STATION ROAD CROSS HILLS KEIGHLEY, WEST YORKSHIRE BD20 7DT	<b>Order Contact</b> Name: Leah McBride Phone: 01563 827457 <a href="mailto:Leah.McBride@aapct.scot.nhs.uk">Leah.McBride@aapct.scot.nhs.uk</a> hs.uk	<b>Delivery</b> LEAH MCBRIDE A1086-CLINICAL PHYSICS UNIVERSITY HOSPITAL CROSSHOUSE KILMARNOCK, EAST AYRSHIRE KA2 0BE

### Delivery Information

<b>Order Type:</b>	Direct Ship
<b>Carrier:</b>	Not Selected -Not Selected
<b>FOB - Delivery Terms:</b>	Not Selected -Not Selected

### Payment Information

<b>Customer Number:</b>	NK
<b>Payment Terms:</b>	Net 30

Line	Item Type	Item No	Manufacturer No	UOM	Pack Size	Qty	Unit Price	VAT Type	Extended Amt
	Description							Est VAT	
1	Non-Catalogue	QVM140052	QVM140052	Each		1	£84.50	SI	£84.50
	Repair to VM-2500 Capnograph, serial number 60920171, as per quotation QVM140052							£16.90	

**Total Extended Amount:** £84.50

**Total Estimated VAT:** £16.90

**Estimated Gross Amount:** £101.40

### VAT Types

Key	Description	Estimated VAT
SI	SI - STD IRRECOVERABLE	£16.90

### CONDITIONS OF ORDER

Unless specified, this order is subject to the Scottish Healthcare Supplies Conditions of Contract for the Purchase of Goods and Services. No responsibility will be accepted for goods and/or services delivered to any point other than that specified on this order. The above Order Number MUST be quoted on all advice notes, delivery notes, invoices, correspondence and acknowledgements. Any alteration in quantity or price must be confirmed in writing by the buying officer. All goods must be accompanied by a delivery note clearly showing the delivery address. Only Original Equipment Manufacturers parts are to be provided unless an alternative has been approved by the ordering department Designated Purchasing Officer.