

Service Repair Sheet SRS68311

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Sudath Weeraman

Prime Lanka Associate

9410718732285

00006714

sudathweeraman17@gmail.com

08/Nov/2022

Robert Connor

Viamed

Warranty

**VIAMEDclean**

**Goods In Only**  
Decontamination  
certificate provided  
by customer ☐

Cleaned by Viamed,  
if no declaration certificate  
from customer ☐

Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

**Goods Out Only**

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

Notes 13/Oct/2022 Kate Griffiths

13/Oct/2022 Kate Griffiths

MAX-250E sensor faulty, under warranty. S/n: GL08399226

08/Nov/2022 Robert Connor

Received 1 x MAX-250E s/n GL08399226

Ready For quote

Repair Complete Signed

CGreen 14.11.22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35524	Oxygen Sensor	0110429	GL08399226	Yes

0140013 x 1 FOC  
old S/N, SRS, SRN

0110429 x 1 FOC  
new S/N, SRS, SRN

~~EXW~~ EXW - ship with next order  
cg 14.11.22



"Bringing quality to life."

No: 57/8, P.B. Alwis Perera Mawatha, Katubedda,  
Moratuwa, Sri Lanka.

+94 071 873 2285 / +94 011 345 9456

011 262 4324

primelanka07@gmail.com  
sudathweeraman17@gmail.com

27 October 2022

The Repair Team.  
Viamed LTD, No.15, Station Road, Cross Hills, Keighley  
West Yorkshire, BD20 7DT  
United Kingdom.

Dear Sir,

The warranty replacement notice, for Oxygen sensor model MAX-250E  
Please note below details for your reference.

Model – Oxygen Sensor MAX-250E

1. S/N - GL08399226

Return Reference No. SRS-68311

Thank you,

You're faithfully

S.J. Weeraman

Prime Lanka Associates  
No.57/8, P.B.Alwis Perera Mawatha  
Katubadda, Moratuwa  
Sri Lanka.

Service Repair Sheet 68311

Contact Name

Company/ Hospital Name

Direct Phone

Opera Account

Email

Date Received

Booked in By

Sudath Weeraman

Prime Lanka Associate

9410718732285

00006714

sudathweeraman17@gmail.com

08/Nov/2022

Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35524	0110429	GL08399226	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110429

Replaced under warranty with S/N HE98699088

---