Service Repair Sheet SRS68322

Contact Name

Mark Evans Royal United Hospitals Bath

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received Booked in By

Main Company Type Return

01225824140

01225 428331

00000350 mark.evans7@nhs.net

CVM132142 17/Nov/2022

Robert Connor

Viamed Warranty

Goods In Only Decontamination certificate provided by customer  Cleaned by Viamed,
Cleaned by Viamed,
if no declaration certificate from customer Signed:

Date: -

Notes 07/Nov/2022 Aqib Majeed

0111263- max 02 me oxygen monitor- wanting to return as one of the switches stopped working, still under warranty 07/Nov/2022 Aqib Majeed

GC48099095

Received 1 x MAXOME s/n GC48099095, with coiled cable 1746898, MAX550E s/n GC25399092, and flow diverter.

Ready For quote

Repair Complete Signed

CG1801 22.11.22

SRN	Equipment	Stock Ref	Serial Number	Warranty	
CALL ASSAULT	MCC Te 4 - 40-41 - 4 - 4	0111263	GC48099095	Yes	
	Oxygen Sensor	0110452	GC25399092	Yes	2 Part.
		0131700	Tracking8	Yes =	7 00

0140050 × 12 60

faulty

0111263 × 1 0 EO. New SIN, 800,505 warranty Replacement

0140011 × 1 260 - SRN 39536 SIN, SRS, SEN

Print date

## Royal United Hospitals Bath NHS

**NHS Foundation Trust** 

Medical Equipment Management Service

Dispatch note	external	service
Dispatch note	CALCITION	SCI AICC

Our reference

263836

Supplier

VIAMED LTD

Order date

07/11/2022

Our Reference

15 STATION ROAD, CROSS HILLS Address

KEIGHLEY, W YORKSHIRE BD20 7DT

Contact person

MARK EVANS

Your reference

SRS68322 01535 634542

Phone

Email

01225 824154

Phone Fax

01535 635582

Fax

Mobile phone

Type of service mark.evans7@nhs.net

Package no

WARRANTY WORK

MEMS no.

50056

Serial no

GC48099095

Device type

OXYGEN MONITOR

MAXTEC

Brand MAX O2 ME

Model Owner

0541

CHILDRENS WARD; RUH

Location

0541

CHILDRENS WARD; RUH

## Message

Hi

The fault with this Max O2 me oxygen monitor is the on/off button has no effect when it's pressed.

Please repair under warranty.

Many thanks

Mark Evans

Return date

Signature //

Before commencing an in-depth repair, could you please advise us by telephone of the likely cost if over £ O • CO by asking for the contact person above. This letter serves as a certificate that the device has been decontminated to standard local protocols. PLEASE RETURN ITEM TO DELIVERY ADDRESS BELOW

The goods are to be returned to the address below

Invoice address

Finance Dept, Malvern House -

Building 6

Royal United Hospital

Combe Park BATH BA1 3NG

**Delivery address** 

MEMS - Department A8 ROYAL UNITED HOSPITAL

COMBE PARK

**BATH** BA1 3NG

> This item has been decontaminated

Signature

Service Repair Sheet 68322

Contact Name

Mark Evans

Company/ Hospital Name

Royal United Hospitals Bath

**Direct Phone** General Phone 01225824140 01225 428331

Opera Account

00000350

Email

mark.evans7@nhs.net

Order Number Date Received Booked in By

CVM132142 17/Nov/2022

Robert Connor

Repair

Ref

S/N

**Equipment Type** 

**Under Warranty** 

SRN35534

0111263 GC48099095

Oxygen Monitor

Time: 0 Hour(s)

Parts Replaced

Qty: 1 0111263

Replaced under warranty with S/N HH77699007 and cable 2076509

edited

Repair SRN35536 Ref

S/N 0110452 GC25399092

Equipment Type

**Under Warranty** 

Oxygen Sensor

No Fault Found Time: 0 Hour(s)

No fault found

Repair

Ref

S/N

**Equipment Type** 

**Under Warranty** 

SRN35537

0131700 Tracking8

Oxygen Monitor Cable

Time: 0 Hour(s)

Replaced as part of the package with MAXO2ME S/N HH77699007 and cable 2076509