



Stornoway Subsea Ltd

 CID17142 Opera Type: **Vandagraph Retail**

Stornoway Subsea Ltd Nacula 8C, Steinish, Isle of Lewis, , HS2 0AA,
Scotland

Tel **07880892936** GBP Retail Price List Vandagraph (0010)



Add Issue

Proforma Credit Limit 0.00GBP

 Account Home

 Main Details

Account Memos

Sales History

Purchase Orders

Stock References

 Cust./Supp. Returns

Service Visits

Distributor Agreements

Documents
Files

 Linked Issues

Regulatory Agreements

SRS68320

SRS Created : 02 Nov 2022

Created By Robert Connor

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

Handle with care

Add Items to Supplier Returns Box

Add

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Service Repair Sheet 68320		Notes
Company / Hospital	Stornoway Subsea Ltd	02/Nov/2022 Robert Connor
Contact Name	Don Macdonald	02/Nov/2022 Robert Connor Received 1 x tek-ox s/n TX 2611, with yellow case, blue tee, flow diverter, and integrated sensor. For repair.
Department		20/Nov/2022 Catherine Spence
Position		In engineers room
Company Phone	07880892936	
Direct Phone		
Opera Account		
Email	donmacdonald21@hotmail.com	
Order Number		
Viamed ORD Number		
Date Received Into building	02 Nov 2022	
Type	Quote Before Repair	

Issues?

Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN35514	Vandagraph Tek Ox	7910211	 1183092	TX2611	Oxygen Analyser Tek-Ox	No	No	Unfinished		00:00

Currently Viewing ITEM SRN35514 Vandagraph Tek Ox 7910211 TX2611 Oxygen Analyser Tek-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	Non added Yet	Non added Yet

-