

Service Repair Sheet SRS68329

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Daniel Lodge

Royal Liverpool University Hospital

Medical Engineering Department

01517062079

01517062000

00002690

daniel.lodge@liverpoolft.nhs.uk

05/Dec/2022

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 14/Nov/2022 Kate Griffiths

14/Nov/2022 Kate Griffiths

Returning AX300 under warranty, s/n 339159. Constantly goes to zero.

05/Dec/2022 Robert Connor

Received 1 x AX300 s/n 339159, with 3 x AA battery, coiled cable s/n 0010254, R17MED s/n 605863, and flow diverter.

Ready For quote

Repair Complete Signed

Steve N. agreed to replace cable FOC
CG 15-12-22

CGreen 15-12-22

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35543	Oxygen Monitor	0111230	339159	Yes
SRN35544	Oxygen Monitor Cable	0131202	0010254	22
SRN35545	Oxygen Sensor	0110017	605863	22

01400006 x 1 @ £0.
S/N, SRS, SRN
NO fault found.

01400011 x 1 @ £0
S/N, SRS, SRN
NO fault found.

01400025 x 1 @ £0
S/N, SRS, SRN

0131202 x 1 @ £0
New S/N, SRS, SRN

UPS x 1 @ £0.

under warranty
no - SRS68329

Return Address - Medical Engineering Department,
Royal Liverpool University Hospital,
Prescot Street,
Liverpool,
L7 8XP

Service Repair Sheet 68329

Contact Name

Daniel Lodge

Company/ Hospital Name

Royal Liverpool University Hospital

Department

Medical Engineering Department

Direct Phone

01517062079

General Phone

01517062000

Opera Account

00002690

Email

daniel.lodge@liverpoolft.nhs.uk

Date Received

05/Dec/2022

Booked in By

Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35543	0111230	339159	Oxygen Monitor	No Fault Found Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35544	0131202	0010254	Oxygen Monitor Cable	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 0131202

Replaced under warranty with S/N 0010737

Repair	Ref	S/N	Equipment Type	
SRN35545	0110017	605863	Oxygen Sensor	No Fault Found Time :0 Hour(s)
