

Service Repair Sheet SRS68331

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Kinga Frolyo

H.S Medplan KFT (EURO)

+36 1 361 0136

+361 01363610272

00006106

kinga.frolyo@medplan.hu

21/Dec/2022

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only
Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐
Signed: _____
Date: _____

Goods Out Only
Cleaned by Viamed before
returning to customer
Signed: _____
Date: _____

Notes 22/Nov/2022 Ryan Swaine

22/Nov/2022 Ryan Swaine

R-22MED sn: 622760 and 786502. One is reported to be reading high and the other has no output.

21/Dec/2022 Robert Connor

Received 2 x R22MED s/n 622760, 786502

Ready For quote

Repair Complete Signed

CGreen 4-1-23

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN35581	Oxygen Sensor	0110022	622760	Yes
SRN35582	Oxygen Sensor	0110022	786502	Yes

0140013 x 1 FOC
Old S/N, SRS, SRN.

0110022 x 1 FOC
New S/N, SRS, SRN

0140011 x 1 FOC
S/N, SRS, SRN

UPS x 1 FOC.



INT/AIR

1

Con No. 281129748		Service Express (ND) Options (EDR) EDR
Piece 1 of 1	Weight 0.30kg	
Customer Reference SRS68331 S/R Account No 000015098		Origin BUD Pickup Date 20 Dec 2022
Sender H.S.-medplan Kft. Nagyterenyi ut 30. Budapest 1222 HU		Routing CDG EMA
Receiver Ryan Swaine Viamed Ltd 15 Station Road Keighley BD20 7DT GB		Sort
Postcode / Cluster Code	BD20 7DT	Dest/ Depot BA4 21
Delivery instructions: SRS68331		



110028112974801198423000000

Service Repair Sheet 68331

Contact Name

Company/ Hospital Name

Direct Phone

General Phone

Opera Account

Email

Date Received

Booked in By

Kinga Frolyo

H.S Medplan KFT (EURO)

+36 1 361 0136

+361 01363610272

00006106

kinga.frolyo@medplan.hu

21/Dec/2022

Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35581	0110022	622760	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110022

Replaced under warranty with S/N 824851

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN35582	0110022	786502	Oxygen Sensor	

No Fault Found

Time :0 Hour(s)

No fault found.
